



**DN62VWT**

report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER
Colour	Green
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-08
Pictures	47
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-02-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	13
Total items failed	6

MOT #13	2024-02-13 16:58
MOT test number	578125173722
Result	✓ Passed
Next expiry date	2025-02-12

MOT #12	2024-02-12 14:43
MOT test number	305110730147
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2023-05-23 08:44
MOT test number	739596996908
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.9mm (5.2.3 (e))
Advice	Engine covers fitted
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2. mm (5.2.3 (e))

**MOT #10** 2022-03-04 18:01**MOT test number** 124836445191**Result** ✓ Passed**Advice** Offside Front tyre, wearing on outer edge**MOT #9** 2021-03-12 09:56**MOT test number** 136451679769**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Tyre slightly damaged/cracking or perishing both rear tyres cracked between tread blocks  
205x60x16 (5.2.3 (d) (ii))**MOT #8** 2020-03-11 14:36**MOT test number** 749781273682**Result** ✓ Passed**Advice** Tyre slightly damaged/cracking or perishing all 4 tyres cracked between tread blocks (5.2.3 (d)  
(ii))**Advice** Items removed from driver's view prior to test**MOT #7** 2019-03-14 09:03**MOT test number** 383609014152**Result** ✓ Passed**MOT #6** 2018-03-13 12:29**MOT test number** 281906765619**Result** ✓ Passed**MOT #5** 2017-03-06 11:03**MOT test number** 861731654931**Result** ✓ Passed

**MOT #4** 2017-03-06 11:03**MOT test number** 675846844956**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**MOT #3** 2016-03-16 14:46**MOT test number** 631265397561**Result** ✓ Passed**MOT #2** 2016-01-05 15:47**MOT test number** 232540550598**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords side wall damage (4.1.D.1a)**Advice** Both front tyres perished on side walls**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords side wall damage (4.1.D.1a)**MOT #1** 2015-11-23 09:30**MOT test number** 529178063917**Result** ✓ Passed**Advice** All tyres worn on sidewalls



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
12 February 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	12 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-17
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2012-12-17	25 mi
Registration #2	2015-11-23	16.399 mi
Registration #3	2016-01-05	17.156 mi
Registration #4	2016-03-16	17.164 mi
Registration #5	2017-03-06	26.980 mi
Registration #6	2017-03-06	26.980 mi
Registration #7	2018-03-13	34.254 mi
Registration #8	2019-03-14	38.405 mi
Registration #9	2020-03-14	38.405 mi
Registration #10	2021-03-14	38.405 mi
Registration #11	2022-03-14	38.405 mi
Registration #12	2023-03-14	38.405 mi
Registration #13	2024-03-14	38.405 mi
Registration #14	2025-03-14	38.405 mi
Registration #15	2026-03-14	38.405 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1265 kg
Max. allowed weight	1775 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	A190J296