





report date: 2024-03-28

General information

| Make | VAUXHALL |
|---------------------|----------------|
| Model | AGILA S |
| Colour | Blue |
| Year of manufacture | 2011 |
| Top speed | 109 mph |
| 0 - 60 mph | 12.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 92 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 4.800 rpm |
| Engine capacity | 1.242 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2022-07-03

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

| MOT history | M | OT | history |
|-------------|---|----|---------|
|-------------|---|----|---------|

Fail

| MOT expiry date | 2024-07-23 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 7 |
| Total items failed | 6 |

| MOT #15 | 2023-06-29 09:50 |
|------------------|------------------|
| MOT test number | 917060401169 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-23 |

| MOT #14 | 2022-07-05 07:42 |
|-----------------|------------------|
| MOT test number | 830527019407 |
| Result | ✓ Passed |

| MOT #13 | 2022-07-04 11:03 |
|-----------------|------------------|
| MOT test number | 110083526558 |
| Result | X Failed |
| | |

| MOT test number | 622768204324 |
|-----------------|------------------|
| MOT #12 | 2021-06-25 11:02 |
| | |

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

| Result | ✓ Passed |
|--------|----------|

| MOT #11 | 2021-06-25 08:55 |
|-----------------|------------------|
| MOT test number | 343527897707 |
| Result | × Failed |

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9 2019-07-19 08:29 **MOT** test number 445701727849 Result ✓ Passed **MOT** #8 2018-07-28 09:46 **MOT** test number 969851576231 Result ✓ Passed **Advice** Nearside front tyre worn to 1.6mm legal limit **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number
923040033602

Result

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside front tyre worn to 1.6mm legal limit

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #6
 2018-03-12 14:10

 MOT test number
 495298510674

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

| MOT #5 | 2017-03-21 11:46 |
|--|------------------|
| MOT test number | 216981389834 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2016-03-30 09:24 |
| MOT test number | 856472252058 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2015-03-10 16:05 |
| MOT test number | 819259165006 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Notice All four tyres perished | |

| MOT #2 | | 2014-03-18 08:54 |
|-------------------------|-------------------------------------|------------------|
| MOT test number | | 317967774074 |
| Result | | ✓ Passed |
| | | |
| MOT #1 | | 2014-03-18 08:54 |
| MOT test number | | 318057874050 |
| Result | | X Failed |
| Pass with rectification | Offside Headlamp aim too low (1.8) | |
| Pass with rectification | Nearside Headlamp aim too low (1.8) | |

CarCheck.co.uk page 5/12



EA11BHEreport date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 64 |
| MOT expiry date | 23 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date Category Type Damage 2

Category

Type

Date



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



EA11BHE report date: 2024-03-28

Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloaner. | |
| THE PARTY OF THE P | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | NK NK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |
| | |
| | |
| | |

CarCheck.co.uk page 9/12



EA11BHE report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2011-03-30 |
| Last registration | 2023-06-29 |
| Complete history | See info |



| Registration #1 | 2011-03-30 | 8 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-03-18 | 14.413 mi |
| Registration #3 | 2015-03-10 | 23.060 mi |
| Registration #4 | 2016-03-30 | 32.469 mi |
| Registration #5 | 2017-03-21 | 41.964 mi |
| Registration #6 | 2018-03-12 | 51.862 mi |
| Registration #7 | 2018-07-27 | 55.548 mi |
| Registration #8 | 2018-07-28 | 55.548 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | D.777 es |
| Registration #15 | | 11.777 es |
| | | |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 11/12



EA11BHE report date: 2024-03-28

Safety ratings

| NCAP rating | **** |
|-------------|------|
|-------------|------|

Video <u>see crash video</u>



Dimensions & weight

| Width | 1932 mm |
|---------------------|---------|
| Height | 1590 mm |
| Length | 3740 mm |
| Wheel base | 2360 mm |
| Kerb weight | 990 kg |
| Max. allowed weight | 1485 kg |

Additional information

| Fuel delivery | Multi-Point Injection |
|-----------------|-----------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | 1331429 |

CarCheck.co.uk page 12/12