



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K







Internet history

Entry 1

Date	2021-07-17
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	8

## MOT #14 2023-06-23 10:42

MOT test number 227460810284

Result ✓ Passed

Next expiry date 2024-06-27

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Rear fuel pipes corroded

## MOT #13 2022-06-17 08:38

MOT test number 815646248196

Result ✓ Passed

## MOT #12 2021-06-28 08:57

MOT test number 745184420041

Result ✓ Passed**Advice** Central Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Minor** Nearside Front Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11** 2020-05-14 09:33**MOT test number** 838805135795**Result** ✓ Passed**MOT #10** 2019-05-01 07:41**MOT test number** 396173602171**Result** ✓ Passed**Advice** Park brake balance only just met the requirement**MOT #9** 2019-05-01 07:41**MOT test number** 482305360029**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure (2.1.3 (g) (ii))**Advice** Park brake balance only just met the requirement**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2018-01-11 12:21**MOT test number** 946407136895**Result** ✓ Passed**Advice** Nearside rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.6b)**MOT #7** 2017-01-18 14:22**MOT test number** 856743170744**Result** ✓ Passed**Advice** N/s/r wheel bearing noisy

**MOT #6** 2017-01-12 09:31**MOT test number** 220444500126**Result** ✗ Failed**Fail** Rear parking (secondary) brakes imbalanced (3.7.B.6b)**Fail** Nearside rear parking (secondary) brake grabbing severely (3.7.B.6b)**Advice** N/s/r wheel bearing noisy**Advice** Nearside Play in steering rack inner joint(s)**MOT #5** 2016-01-20 16:33**MOT test number** 195080146688**Result** ✓ Passed**Advice** Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)**MOT #4** 2015-01-22 10:57**MOT test number** 329432825057**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight play in n/s/f inner rack joint**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake discs corroded**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #3** 2014-01-21 14:45**MOT test number** 835451124069**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2014-01-21 14:45
MOT test number	659851724052
Result	✗ Failed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1	2012-09-17 16:51
MOT test number	319731162478
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
27 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	27 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-03-31
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	22 mi
Registration #2	2012-09-17	33.852 mi
Registration #3	2014-01-21	44.451 mi
Registration #4	2015-01-22	48.255 mi
Registration #5	2016-01-20	51.478 mi
Registration #6	2017-01-12	54.346 mi
Registration #7	2017-01-18	54.411 mi
Registration #8	2018-01-11	57.573 mi
Registration #9	2019-01-11	60.735 mi
Registration #10	2020-01-11	63.897 mi
Registration #11	2021-01-11	67.059 mi
Registration #12	2022-01-11	70.221 mi
Registration #13	2023-01-11	73.383 mi
Registration #14	2024-01-11	76.545 mi
Registration #15	2025-01-11	79.707 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	D4CB8394448