



report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D5 SE LUX
Colour	Silver
Year of manufacture	2011
Top speed	143 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	202 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





MOT history

MOT expiry date	2025-01-11
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	23
Total items failed	0

MOT #14	2024-01-12 15:35
MOT test number	721435905518
Result	✓ Passed
Next expiry date	2025-01-11
Advice	Front Tyre worn close to legal limit/worn on edge both front tyres worn on inside edges (5.2.3 (e))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #13	2024-01-11 11:02
MOT test number	673414826074
Result	✗ Failed
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
MAJOR	Road wheel fixing missing one wheel bolt missing off each wheel (5.2.1 (a) (i))
Advice	Front Tyre worn close to legal limit/worn on edge both front tyres worn on inside edges (5.2.3 (e))
MAJOR	Windscreen washer not working (3.5 (a))
Advice	Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #12** 2023-01-05 15:05**MOT test number** 262352854140**Result** ✓ Passed**MOT #11** 2021-12-24 12:13**MOT test number** 445768938923**Result** ✓ Passed**MOT #10** 2021-09-20 13:33**MOT test number** 343669927584**Result** ✓ Passed**MOT #9** 2020-07-29 14:49**MOT test number** 551081799306**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge edges worn smooth (5.2.3 (e))**MOT #8** 2020-07-29 08:21**MOT test number** 781674634330**Result** ✗ Failed**MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge edges worn smooth (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2019-06-28 11:11**MOT test number** 518077965305**Result** ✓ Passed

**MOT #6** 2019-06-28 10:04**MOT test number** 712803230686**Result** ✗ Failed

- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Offside Rear Suspension component pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Suspension component pin or bush excessively worn trailing arm (5.3.4 (a) (i))

MOT #5 2018-06-26 11:06**MOT test number** 571936930470**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2017-07-04 09:26**MOT test number** 648643709836**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit 2.4mm (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit 2.5mm (4.1.E.1)

MOT #3 2016-07-05 14:26**MOT test number** 967215138969**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-06-23 10:15**MOT test number** 407504975113**Result** ✓ Passed



MOT #1	2014-06-13 13:07
MOT test number	247714764123
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
29 February 2024

✓

MOT

Expires:
11 January 2025

Tax status	Expired at 29 February 2024
Days left	61 days too late
MOT expiry date	11 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-04-20
Last registration	2024-01-12
Complete history	See info



Registration #1	2011-04-20	14 mi
Registration #2	2014-06-13	35.557 mi
Registration #3	2015-06-23	49.117 mi
Registration #4	2016-07-05	60.600 mi
Registration #5	2017-07-04	72.407 mi
Registration #6	2018-06-26	85.321 mi
Registration #7	2019-06-28	97.254 mi
Registration #8	2019-06-28	97.254 mi
Registration #9	2019-06-28	97.254 mi
Registration #10	2019-06-28	97.254 mi
Registration #11	2019-06-28	97.254 mi
Registration #12	2019-06-28	97.254 mi
Registration #13	2019-06-28	97.254 mi
Registration #14	2019-06-28	97.254 mi
Registration #15	2019-06-28	97.254 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2778 mm
Kerb weight	1674 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	974909