



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	440 Nm at 2.500 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L





Internet history

Entry 4

Date	2023-12-05
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 3

Date	2023-05-08
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 2

Date	2023-05-06
Pictures	2
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-02
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	30
Total items failed	7

MOT #16	2023-10-03 15:06
MOT test number	319824659355
Result	✓ Passed
Next expiry date	2024-10-02

MOT #15	2023-03-29 15:16
MOT test number	263901062184
Result	✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #14**

2023-03-29 15:16

MOT test number

312923094168

Result**✗ Failed**

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Offside Rear Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13

2022-03-08 11:47

MOT test number

345525747161

Result**✓ Passed**

- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #12

2022-03-08 11:47

MOT test number

994853296708

Result**✗ Failed**

- Pass with rectification** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #11

2021-03-04 15:50

MOT test number

429474403331

Result**✓ Passed**

**MOT #10** 2020-10-26 15:34**MOT test number** 496777961745**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2020-06-02 11:47**MOT test number** 371543454567**Result** ✓ Passed**Advice** Nearside Rear brake binding slightly**MOT #8** 2020-06-01 11:28**MOT test number** 822282919605**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 215/70/16c (5.2.3 (d) (i))**Advice** Nearside Rear brake binding slightly**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn to 3mm and has a nail in it (5.2.3 (e))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on edge (5.2.3 (e))**MOT #7** 2019-05-01 09:01**MOT test number** 719025677129**Result** ✓ Passed**MOT #6** 2018-04-30 09:51**MOT test number** 508414417482**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #5	2017-05-04 14:29
MOT test number	775921885509
Result	✓ Passed
Advice	Unable to check rearmost seatbelts + n/s/r seatbelt due to childseats

MOT #4	2017-05-03 15:16
MOT test number	255007708565
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Advice	Unable to check rearmost seatbelts + n/s/r seatbelt due to childseats
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 215/70/16c (4.1.D.1a)

MOT #3	2016-04-15 15:01
MOT test number	921098955921
Result	✓ Passed
Advice	Engine under tray fitted not allowing full inspection

MOT #2	2016-04-15 15:01
MOT test number	747816366235
Result	✗ Failed
Advice	Engine under tray fitted not allowing full inspection
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)



MOT #1	2015-04-30 14:49
MOT test number	168060025167
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Interior mirror missing
Notice	N/s/r tyre 3.0mil



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
2 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	2 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2023-03-28
Current registration	XXXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2012-05-01
Last registration	2023-10-03
Complete history	See info



Registration #1	2012-05-01	14 mi
Registration #2	2015-04-30	41.974 mi
Registration #3	2016-04-15	56.543 mi
Registration #4	2016-04-15	56.543 mi
Registration #5	2017-05-03	64.281 mi
Registration #6	2017-05-04	64.281 mi
Registration #7	2018-04-30	71.751 mi
Registration #8	2019-05-01	78.796 mi
Registration #9	2020-06-01	84.485 mi
Registration #10	2020-06-02	84.485 mi
Registration #11	2020-10-26	86.655 mi
Registration #12	2020-10-26	86.655 mi
Registration #13	2020-10-26	86.655 mi
Registration #14	2020-10-26	86.655 mi
Registration #15	2020-10-26	86.655 mi
Registration #16	2020-10-26	86.655 mi
Registration #17	2020-10-26	86.655 mi
Registration #18	2020-10-26	86.655 mi
Registration #19	2020-10-26	86.655 mi
Registration #20	2020-10-26	86.655 mi
Registration #21	2020-10-26	86.655 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Engine number	D4CBC995094
---------------	-------------