



report date: 2022-08-09

General information

Make	FIAT
Model	BARCETTA CONVERTIBL
Colour	Orange
Year of manufacture	1997
Top speed	124 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	164 Nm at 4.300 rpm
Engine capacity	1.747 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	33.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-12
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	37
Total items failed	19

MOT #24	2023-10-13 08:53
MOT test number	999863718709
Result	✓ Passed
Next expiry date	2024-10-12

MOT #23	2022-09-16 13:53
MOT test number	304694424754
Result	✓ Passed

MOT #22	2021-10-05 13:42
MOT test number	195202513330
Result	✓ Passed

Advice Underside of vehicle shows slight corrosion

MOT #21	2021-09-14 14:46
MOT test number	244600566050
Result	✗ Failed

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front and rear suspension components have slight corrosion

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #20** 2020-08-10 13:21**MOT test number** 593274039899**Result** ✓ Passed**MOT #19** 2019-05-31 13:52**MOT test number** 391223892894**Result** ✓ Passed**Advice** Corrosion hole offside rear inner wheel arch**MOT #18** 2016-10-18 16:37**MOT test number** 710289387089**Result** ✓ Passed**MOT #17** 2016-10-05 13:41**MOT test number** 204133174702**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings Floorpan (6.1.B.2)**Fail** Offside Headlamp aim too low (1.8)**MOT #16** 2015-09-05 09:15**MOT test number** 621689750743**Result** ✓ Passed**MOT #15** 2015-09-03 11:15**MOT test number** 902498491558**Result** ✗ Failed**Fail** Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Offside Rear wheel bearing rough when rotated (2.6.1)



MOT #14	2014-05-09 15:05
MOT test number	309229824144
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #13	2014-04-10 12:05
MOT test number	185060204170
Result	✗ Failed
Advice	Nearside Shock absorber has a light misting of oil (2.7.3)
Fail	Nearside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)
Fail	Offside Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
Fail	Offside Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

MOT #12	2012-12-12 10:17
MOT test number	645577042310
Result	✓ Passed

MOT #11	2011-12-13 12:46
MOT test number	728937441333
Result	✓ Passed

MOT #10	2011-12-13 12:46
MOT test number	388257841396
Result	✗ Failed
Pass with rectification	Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #9**

2011-10-27 16:56

MOT test number

986880601310

Result

✓ Passed

- Notice** Offside front tyre sidewall cracking
- Notice** Offside outer track rod end joint cover split/missing
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front tyre sidewall cracking
- Notice** Nearside outer track rod end joint cover split/missing
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #8

2009-10-12 14:06

MOT test number

164065689214

Result

✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #7**

2009-10-09 12:27

MOT test number

844502289239

Result

✗ Failed

- Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Fail** Offside Rear Seat belt anchorage prescribed area is excessively corroded (5.2.6)
- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

2008-08-01 09:31

MOT test number

463054618218

Result

✓ Passed

- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Corrosion to front floor but not excessive

MOT #5

2007-07-24 09:33

MOT test number

342185707447

Result

✓ Passed

- Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Notice** Both front tyres scrubbing on inner edge
- Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive (5.2.6)

**MOT #4** 2006-08-22 11:10**MOT test number** 472444436286**Result** ✓ Passed**Notice** Fuel cap not tested,unable to open.**MOT #3** 2006-02-02 16:43**MOT test number** 314403336076**Result** ✓ Passed**MOT #2** 2006-02-02 15:01**MOT test number** 322153136093**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Oil leak**Advice** Steering column top bearing slightly worn (2.1.2c)**Notice** Both front and o/s/r tyre sidewalls cracking**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Notice** Corrsion starting to form around o/s/f floor area**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #1**

2006-01-30 15:21

MOT test number

553850036083

Result**✗ Failed****Fail**

Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice

Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice

(walls splitting on both front tyres)

Fail

Nearside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice

Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
12 October 2024

Tax status		Valid until 1 June
Days left		64
MOT expiry date		12 October 2024
Full MOT history		See MOT history



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-08-29
Current registration	
Plate since	2019-08-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	1997-11-14
Last registration	2023-10-13
Complete history	See info



Registration #1	1997-11-14	27 mi
Registration #2	2006-01-30	68.536 mi
Registration #3	2006-02-02	68.537 mi
Registration #4	2006-02-02	68.537 mi
Registration #5	2006-08-22	68.613 mi
Registration #6	2007-07-24	69.908 mi
Registration #7	2008-08-01	69.919 mi
Registration #8	2009-10-09	69.926 mi
Registration #9	2009-10-12	69.927 mi
Registration #10	2011-10-27	70.351 mi
Registration #11	2011-12-13	70.370 mi
Registration #12	2012-12-12	75.566 mi
Registration #13	2014-04-10	80.451 mi
Registration #14	2015-05-20	81.377 mi
Registration #15	2016-05-20	81.377 mi
Registration #16	2017-05-20	81.377 mi
Registration #17	2018-05-20	81.377 mi
Registration #18	2019-05-20	81.377 mi
Registration #19	2020-05-20	81.377 mi
Registration #20	2021-05-20	81.377 mi
Registration #21	2022-05-20	81.377 mi
Registration #22	2023-05-20	81.377 mi
Registration #23	2024-05-20	81.377 mi
Registration #24	2025-05-20	81.377 mi
Registration #25	2026-05-20	81.377 mi



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1640 mm
Height	1260 mm
Length	3916 mm
Wheel base	2275 mm
Max. allowed weight	2400 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	0716530