



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI S
Colour	Grey
Year of manufacture	2008
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg
CO2 emission	148 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-10-02
Pictures	6
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-30
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	25
Total items failed	6

MOT #15	2023-10-31 15:47
MOT test number	643076192363
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2023-10-30 14:08
MOT test number	736725206914
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13	2022-09-30 11:12
MOT test number	136592816432
Result	✓ Passed

**MOT #12** 2021-10-01 09:47**MOT test number** 724365579057**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-12-03 09:15**MOT test number** 920354866155**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-12-03 09:15**MOT test number** 461478057932**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too far to the left (4.1.2 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2019-06-03 14:12**MOT test number** 523804598875**Result** ✓ Passed**MOT #8** 2018-05-24 07:56**MOT test number** 841058048019**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

**MOT #7** 2017-05-30 08:28**MOT test number** 786435993260**Result** ✓ Passed**MOT #6** 2016-05-23 09:44**MOT test number** 857104903384**Result** ✓ Passed**MOT #5** 2015-05-30 10:14**MOT test number** 438010155144**Result** ✓ Passed**MOT #4** 2014-05-27 13:43**MOT test number** 596037844103**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** N/s/r tyre just starting to out shape inside edge**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-05-28 17:04**MOT test number** 188378743142**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #2**

2013-05-28 12:11

MOT test number

759238043180

Result**✗ Failed**

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1

2012-05-29 15:50

MOT test number

609330552142

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
30 October 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GK58OFU
Plate since	2024-03-29
Current registration	 GK58OFU
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-15
Last registration	2023-10-31
Complete history	See info



Registration #1	2008-09-15	7 mi
Registration #2	2012-05-29	20.845 mi
Registration #3	2013-05-28	24.818 mi
Registration #4	2013-05-28	24.818 mi
Registration #5	2014-05-27	29.377 mi
Registration #6	2015-05-30	33.184 mi
Registration #7	2016-05-23	36.565 mi
Registration #8	2017-05-30	38.934 mi
Registration #9	2018-05-24	41.827 mi
Registration #10	2019-05-29	45.377 mi
Registration #11	2020-05-29	49.377 mi
Registration #12	2021-05-29	53.377 mi
Registration #13	2022-05-29	57.377 mi
Registration #14	2023-05-29	61.377 mi
Registration #15	2023-10-31	65.377 mi
Registration #16	2023-10-31	65.377 mi
Registration #17	2023-10-31	65.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
-----------------	---

Engine number BXE B13128