



report date: 2024-03-29

General information

Make	MAZDA
Model	2 SPORT
Colour	Black
Year of manufacture	2009
Top speed	117 mph
0 - 60 mph	10.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	137 Nm at 4.000 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-11-16
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	21
Total items failed	4

## MOT #14 2023-10-30 12:03

MOT test number 803837573486

Result ✓ Passed

Next expiry date 2024-11-16

- Advice** Front Items removed from driver's view prior to test Phone holder
- Advice** Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i))
- Advice** Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))
- Advice** Steering column universal joint has slight wear or play (2.2.2 (c))
- Advice** Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

## MOT #13 2022-10-31 12:11

MOT test number 940089580315

Result ✓ Passed

- Advice** Nearside Front Outer Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

## MOT #12 2021-11-02 15:22

MOT test number 873631031323

Result ✓ Passed

**MOT #11**

2021-11-02 09:50

**MOT test number**

498309628980

**Result**

✗ Failed

**Fail** Front Windscreen wiper does not clear the windscreen effectively both side (3.4 (b) (ii))**Advice** Rear Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Front Brake pad(s) wearing thin both side (1.1.13 (a) (ii))**MOT #10**

2020-11-17 10:19

**MOT test number**

138139148505

**Result**

✓ Passed

**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge no tread (5.2.3 (e))**MOT #9**

2019-06-24 14:09

**MOT test number**

160971086282

**Result**

✓ Passed

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2018-06-14 10:08

**MOT test number**

390269901269

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-06-14 10:08**MOT test number** 482737128091**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-05-31 14:40**MOT test number** 884527611044**Result** ✓ Passed**MOT #5** 2016-06-15 09:11**MOT test number** 481635298329**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-06-15 09:11**MOT test number** 587514735542**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)**MOT #3** 2015-01-14 12:02**MOT test number** 456874315067**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** O/S Mirror casing damaged



MOT #2	2014-01-02 11:24
MOT test number	666312804044
Result	✓ Passed

  

MOT #1	2012-12-14 12:08
MOT test number	566099142394
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
16 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	16 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-16
Last registration	2023-10-30
Complete history	<a href="#">See info</a>



Registration #1	2009-12-16	16 mi
Registration #2	2012-12-14	22.564 mi
Registration #3	2014-01-02	29.367 mi
Registration #4	2015-01-14	36.770 mi
Registration #5	2016-06-15	47.741 mi
Registration #6	2016-06-15	47.741 mi
Registration #7	2017-05-31	54.221 mi
Registration #8	2018-06-14	60.810 mi
Registration #9	2019-06-20	65.377 mi
Registration #10	2019-06-20	65.377 mi
Registration #11	2019-06-20	65.377 mi
Registration #12	2019-06-20	65.377 mi
Registration #13	2019-06-20	65.377 mi
Registration #14	2019-06-20	65.377 mi
Registration #15	2019-06-20	65.377 mi
Registration #16	2019-06-20	65.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3895 mm
Wheel base	2490 mm
Kerb weight	1030 kg
Max. allowed weight	1460 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZY 529928