



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 GDI S
Colour	White
Year of manufacture	2014
Top speed	111 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	133 BHP
Max. torque	165 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	47.1 mpg
Consumption combined	41.5 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-06-28
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-06-15
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-09
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	22
Total items failed	1

MOT #12	2023-06-09 12:43
MOT test number	490042111075
Result	✓ Passed
Next expiry date	2024-06-09

MOT #11	2023-06-09 09:48
MOT test number	674557209506
Result	✗ Failed
<b>DANGEROUS</b> Front Brake disc in such a condition that it is seriously weakened both side (1.1.14 (a) (ii))	
<b>DANGEROUS</b> Front Brake pad(s) less than 1.5 mm thick both side (1.1.13 (a) (ii))	
<b>MAJOR</b> Windscreen wiper does not clear the windscreen effectively both front wipers (3.4 (b) (ii))	

MOT #10	2022-05-25 13:47
MOT test number	914117992508
Result	✓ Passed
<b>Advice</b> Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))	

**MOT #9** 2022-05-25 10:26**MOT test number** 645088329506**Result** ✗ Failed**Advice** Front Brake disc worn, but not excessively both side (1.1.14 (a) (i))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #8** 2021-06-10 14:15**MOT test number** 934285080764**Result** ✓ Passed**MOT #7** 2021-06-10 08:09**MOT test number** 861904617325**Result** ✗ Failed**DANGEROUS** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2020-09-30 12:10**MOT test number** 295612773754**Result** ✓ Passed**MOT #5** 2019-04-01 15:31**MOT test number** 129352343482**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2019-04-01 09:17**MOT test number** 907101357979**Result** ✗ Failed**Advice** Offside Front Nail in tyre**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Items removed from driver's view prior to test**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-04-26 15:59**MOT test number** 203569669552**Result** ✓ Passed**Advice** Offside Rear Tyre perished cracking between tread**MOT #2** 2018-04-25 15:25**MOT test number** 584841109468**Result** ✗ Failed**Advice** Offside Rear Tyre perished cracking between tread**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** Nearside Rear Tyre perished cracking between tread**Advice** Nearside Rear Nail in tyre**MOT #1** 2017-04-21 13:12**MOT test number** 690093449002**Result** ✓ Passed**Advice** O/S/F + Rear Wipers Torn**Advice** Both Front Tyres At 2mm



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
9 June 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	9 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>SV64LWN</b>
Plate since	2019-03-29
Current registration	<b>SV64LWN</b>
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-01
Last registration	2023-06-09
Complete history	<a href="#">See info</a>



Registration #1	2014-09-01	10 mi
Registration #2	2017-04-21	25.565 mi
Registration #3	2018-04-25	33.348 mi
Registration #4	2018-04-26	33.357 mi
Registration #5	2019-04-01	41.680 mi
Registration #6	2019-04-01	41.680 mi
Registration #7	2020-09-30	53.648 mi
Registration #8	2021-06-10	56.042 mi
Registration #9	2022-06-09	56.042 mi
Registration #10	2022-06-09	56.042 mi
Registration #11	2022-06-09	56.042 mi
Registration #12	2022-06-09	56.042 mi
Registration #13	2022-06-09	56.042 mi
Registration #14	2022-06-09	56.042 mi
Registration #15	2022-06-09	56.042 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FDEZ867300