





General information

Make	PEUGEOT
Model	206 SE
Colour	Silver
Year of manufacture	-
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP	0 < 101 A
Max. torque	133 Nm at 3.250 rpm	101 - 120 ^B _C
Cylinders	4	121 - 140 E
Fuel type	Petrol	141 - 165 F
Consumption city	34.5 mpg	166 - 185 H
Consumption extra urban	57.7 mpg	186 - 225 J
Consumption combined	46.3 mpg	225+ L





Internet history

Ε	ntry	1
	_	

Date

2021-08-10

Pictures

Listing price

View report

5



source: autotrader.co.uk



MOT history

MOT #18	2021-10-03 09:39
MOT test number	799561873388
Result	✓ Passed
Next expiry date	2022-10-02
Advice Offside Direction indicator slightly discoloured (4.4.3 (a))	
Advice Nearside Direction indicator slightly discoloured (4.4.3 (a))	
Advice Oil leak, but not excessive signs of oil leak (8.4.1 (a) (i))	

MOT #17		2020-11-04 15:44
MOT test	number	778157673463
Result		✓ Passed
Advice	Rear Inner Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Side repeater slightly discoloured (4.4.3 (a))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #16	2019-05-08 09:44
MOT test number	988960332099
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing old age cracking on sidewall and in tread (5.2.3 (d) (ii))	





MOT #15		2019-05-04 14:12
MOT test	number	149045646274
Result		🗙 Failed
MAJOR	Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice (5.2.3 (d)	Offside Rear Tyre slightly damaged/cracking or perishing old age cracking ((ii))	on sidewall and in tread
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps o	r light sources (4.7.1
MAJOR	Central Front Exhaust has a major leak of exhaust gases at flexible section	(6.1.2 (a))
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively rubber	split (3.4 (b) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
MAJOR	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2	(c))
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively rubbe	er split (3.4 (b) (ii))

MOT #14		2018-05-02 10:52
MOT test	number	514186811171
Result		✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Advice	Offside Rear Tyre cracking	
Advice	Oil leak	



MOT #13	2018-05-02 09:50
MOT test number	591192601938
Result	🗙 Failed
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Oil leak	
Advice Offside Rear Tyre cracking	
Advice Front Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #12		2017-05-08 16:14
MOT test	number	567710880365
Result		✓ Passed
Advice	Offside Rear tyre inner tread edge deteriorated.	
Advice	Nearside Front Outer Track rod end ball joint has slight play (2.2.B.1f)	

MOT #11	2016-04-11 08:17
MOT test number	218321972595
Result	✓ Passed
AdviceExhaust has a minor leak of exhaust gases (7.1.2)AdviceEngine oil leak	

MOT #10	2016-04-11 08:17
MOT test number	856898939391
Result	🗙 Failed
Advice Engine oil leak	
Advice Exhaust has a minor leak of exhaust gases (7.1.2)	
Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)	

GM04LFB

report date: 2024-03-29



MOT #9		2015-04-08 09:53
MOT test	number	907538095075
Result		✓ Passed
Notice	Rear tyres slightly perished.	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Play in steering rack inner joint(s)	
Notice	Offside front tyre worn on outer edge.	
Notice	Oil leak	

MOT #8		2014-03-31 08:15
MOT test	number	946880594010
Result		✓ Passed
Notice	Exhaust rear silencer mounting broken but system still supported.	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #7

MOT test number

Result	V Pa	assed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Side repeater slightly discoloured (1.4.A.2f)	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Exhaust rear silencer has a mounting deteriorated but still supported.	

2013-04-04 09:34

917414193021

GM04LFB

report date: 2024-03-29



GM ()41	LF	B
report o	late: 2	024-03	3-29

2011-04-12 12:43

МОТ #6	2012-04-04 11:11
MOT test number	827385192050
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Play in steering rack inner joint(s)	

MOT #5

Result

MOT #2

Result

MOT test number

MOT test	number
-----------------	--------

MOT test number		819192201122
Result		✓ Passed
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)	
Advice	Nearside Side repeater slightly discoloured (1.4.A.2f)	
Notice	Nearside front tyre worn low on outside edge (raised tread) 175/65/14	

MOT #4	2010-03-23 11:54
MOT test number	620372280013
Result	✓ Passed
MOT #3	2009-04-15 16:00
MOT test number	214525309463

✓ Passed

✓ Passed

2008-05-30 12:19

382011058101





MOT #1		2007-07-11 11:13
MOT test	number	564172997185
Result		✓ Passed
Notice	Nearside rear lamp wet inside	
Notice	Both front wheel trims damaged	
Notice	Offside rear tyre valve dust cap missing	
Advice	Offside Side repeater slightly discoloured (1.4.A.2f)	





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GM04LFB report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-08-23
Last registration	2021-10-03
Complete history	<u>See info</u>



Registration #1	2004-08-23	25 mi
Registration #2	2007-07-11	4.755 mi
-		
Registration #3	2008-05-30	5.704 mi
Registration #4	2009-04-15	6.821 mi
Registration #5	2010-03-23	8.114 mi
Registration #6	2011-04-12	15.433 mi
Registration #7	2012-04-04	26.269 mi
Registration #8	2013-04-04	33.946 mi
Registration #9	2014-03-31	42.323 mi
Registration #10	2015-04-08	49.120 mi
Registration #11		11.117 mi
Registration #12		11.227 est
Registration #13		10.000 mil
Registration #14		00.000 est
Registration #15		10.000 mil
Registration #16		00.000 est
Registration #17		10.200 mil
Registration #18		11.277 est
Registration #19		11.777 est
Registration #20		11.277 est





Car features

S0225	Air conditioning
S0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1652 mm
Height	1426 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1038 kg
Max. allowed weight	1515 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles	2
Engine number	FE010060783