



HYUNDAI



EKI4XDC


report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	50 %
MOT passed	7
Failed MOT tests	7
Total advice items	28
Total items failed	16

MOT #14	2024-04-05 14:12
MOT test number	608652435270
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Nail in tyre
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #13**

2024-03-27 14:55

**MOT test number**

137267094560

**Result****✗ Failed**

- Advice** Nearside Rear Nail in tyre
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #12**

2023-03-02 17:05

**MOT test number**

475998523275

**Result****✓ Passed**

- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))

**MOT #11**

2023-02-21 15:44

**MOT test number**

686838223219

**Result****✗ Failed**

- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2021-08-20 10:27**MOT test number** 786819608917**Result** ✓ Passed**MOT #9** 2021-08-19 15:29**MOT test number** 998358431428**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #8** 2020-11-25 13:16**MOT test number** 953320248242**Result** ✓ Passed

- Advice** No gas blast detected time of test
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Tyre pressure monitoring system illuminated on dash

**MOT #7** 2020-11-18 10:53**MOT test number** 489965557095**Result** ✗ Failed**Fail** Nearside Front Side repeater not working wing mirror led unit (4.4.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** No gas blast detected time of test**Advice** Tyre pressure monitoring system illuminated on dash**MOT #6** 2019-10-02 13:48**MOT test number** 949610787197**Result** ✓ Passed**MOT #5** 2019-10-01 10:33**MOT test number** 364907625411**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #4** 2018-09-11 12:45**MOT test number** 428286990916**Result** ✓ Passed**MOT #3** 2018-09-11 12:45**MOT test number** 487449638483**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #2	2017-07-04 12:11
MOT test number	734746796827
Result	✓ Passed

MOT #1	2017-07-03 11:29
MOT test number	250404548958
Result	✗ Failed
<div><div>Fail</div>Offside Front Windscreen wiper does not clear the windscreen effectively aero (8.2.2)</div> <div><div>Advice</div>Offside Front Tyre worn close to the legal limit 225x60x17 (4.1.E.1)</div> <div><div>Advice</div>Nearside Rear Brake pad(s) wearing thin and offside rear (3.5.1g)</div> <div><div>Fail</div>Nearside Rear Parking brake recording little or no effort (3.7.D.3a)</div> <div><div>Fail</div>Nearside Front Windscreen wiper does not clear the windscreen effectively aero (8.2.2)</div> <div><div>Advice</div>Nearside Front Tyre worn close to the legal limit 225x60x17 (4.1.E.1)</div> <div><div>Advice</div>Nearside Front Brake pad(s) wearing thin and offside front (3.5.1g)</div> <div><div>Advice</div>Nearside Rear Parking (secondary) brake grabbing slightly (3.7.D.3b)</div>	



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
4 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	4 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EK14XDC
Plate since	2019-03-28
Current registration	EK14XDC
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-07-01
Last registration	2024-04-05
Complete history	<a href="#">See info</a>



Registration #1	2014-07-01	8 mi
Registration #2	2017-07-03	25.042 mi
Registration #3	2017-07-04	25.042 mi
Registration #4	2018-09-11	35.184 mi
Registration #5	2018-09-11	35.184 mi
Registration #6	2019-10-01	47.532 mi
Registration #7	2019-10-02	47.555 mi
Registration #8	2020-11-18	58.404 mi
Registration #9	2020-11-18	58.404 mi
Registration #10	2020-11-18	58.404 mi
Registration #11	2020-11-18	58.404 mi
Registration #12	2020-11-18	58.404 mi
Registration #13	2020-11-18	58.404 mi
Registration #14	2020-11-18	58.404 mi
Registration #15	2020-11-18	58.404 mi
Registration #16	2020-11-18	58.404 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDEZ258681