



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Black
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-30
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-06
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #18	2023-09-07 09:50
MOT test number	437198934860
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush. (5.3.4 (a) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #17	2023-09-01 15:10
MOT test number	349737326130
Result	✗ Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Rear bush. (5.3.4 (a) (i))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #16** 2022-08-31 10:22**MOT test number** 362265090779**Result** ✓ Passed**MOT #15** 2021-08-10 13:55**MOT test number** 188503293089**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2021-08-10 08:57**MOT test number** 331959565770**Result** ✗ Failed**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2020-08-04 09:01**MOT test number** 177446073119**Result** ✓ Passed

**MOT #12** 2019-08-06 08:57**MOT test number** 226075662820**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front of arm (5.3.4 (a) (i))**MOT #11** 2018-07-31 09:47**MOT test number** 262270621565**Result** ✓ Passed**MOT #10** 2017-07-26 10:26**MOT test number** 921796907491**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2016-07-19 11:58**MOT test number** 308150790098**Result** ✓ Passed**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2015-07-13 11:54**MOT test number** 645534595185**Result** ✓ Passed

**MOT #7** 2014-07-09 14:30**MOT test number** 376230494181**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear tyres 3mm**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2013-07-08 10:30**MOT test number** 426299383121**Result** ✓ Passed**Notice** All tyres less than 50% worn**MOT #5** 2012-07-18 10:16**MOT test number** 748000102273**Result** ✓ Passed**Advice** Nearside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Inner Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2011-05-05 09:19**MOT test number** 955635021132**Result** ✓ Passed**MOT #3** 2010-05-04 16:40**MOT test number** 780154520181**Result** ✓ Passed



MOT #2	2010-04-28 12:10
MOT test number	282268910103
Result	✗ Failed
Fail	Offside Front Road wheel badly damaged (4.2.A.1a)

MOT #1	2010-03-13 10:48
MOT test number	564662170078
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-04
Last registration	2023-09-07
Complete history	See info



Registration #1	2007-03-04	23 mi
Registration #2	2010-03-13	32.710 mi
Registration #3	2010-04-28	33.643 mi
Registration #4	2010-05-04	33.643 mi
Registration #5	2011-05-05	40.005 mi
Registration #6	2012-07-18	46.350 mi
Registration #7	2013-07-08	50.860 mi
Registration #8	2014-07-09	56.866 mi
Registration #9	2015-07-13	63.102 mi
Registration #10	2016-07-19	68.909 mi
Registration #11	2016-07-19	68.909 mi
Registration #12	2016-07-19	68.909 mi
Registration #13	2016-07-19	68.909 mi
Registration #14	2016-07-19	68.909 mi
Registration #15	2016-07-19	68.909 mi
Registration #16	2016-07-19	68.909 mi
Registration #17	2016-07-19	68.909 mi
Registration #18	2016-07-19	68.909 mi
Registration #19	2016-07-19	68.909 mi
Registration #20	2016-07-19	68.909 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN