



report date: 2024-03-28

## General information

Make	VAUXHALL
Model	TIGRA 16V
Colour	Blue
Year of manufacture	2007
Top speed	112 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-20
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-12-23
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	12
Total items failed	5

MOT #18 2023-11-27 13:18

MOT test number 446306882892

Result ✓ Passed

Next expiry date 2024-12-23

- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17 2022-12-12 12:55

MOT test number 444920725751

Result ✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened N/S & O/S. (1.1.14 (a) (ii))

MOT #16 2021-11-30 17:33

MOT test number 179948514242

Result ✓ Passed

- Advice** Rear Shock absorbers has a slightly worn bush both sides (5.3.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #15** 2021-11-30 13:46**MOT test number** 440019242651**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Brake cable damaged (1.1.15 (a))**Fail** Brake performance not tested (1.2.1 (g))**MOT #14** 2020-12-24 10:36**MOT test number** 584872547505**Result** ✓ Passed**MOT #13** 2020-12-17 11:24**MOT test number** 678303148747**Result** ✗ Failed**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2020-01-22 09:41**MOT test number** 739361426629**Result** ✓ Passed**MOT #11** 2019-01-24 10:33**MOT test number** 771946427379**Result** ✓ Passed

**MOT #10** 2019-01-24 08:48**MOT test number** 726892525161**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2018-01-22 08:31**MOT test number** 810703245860**Result** ✓ Passed**MOT #8** 2018-01-22 08:31**MOT test number** 420767577678**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #7** 2017-01-24 10:37**MOT test number** 416753568054**Result** ✓ Passed**Advice** Oil leak**MOT #6** 2016-01-28 10:21**MOT test number** 921194109862**Result** ✓ Passed**MOT #5** 2015-01-20 10:59**MOT test number** 995520725051**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



<b>MOT #4</b>	2014-01-24 09:58
---------------	------------------

<b>MOT test number</b>	289664524093
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-01-10 13:18
---------------	------------------

<b>MOT test number</b>	416740913052
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2012-01-26 15:34
---------------	------------------

<b>MOT test number</b>	458586122098
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2010-10-22 10:52
---------------	------------------

<b>MOT test number</b>	273805390256
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
23 December 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	23 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-10-29
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2007-10-29	9 mi
Registration #2	2010-10-22	9.289 mi
Registration #3	2012-01-26	13.342 mi
Registration #4	2013-01-10	16.677 mi
Registration #5	2014-01-24	19.608 mi
Registration #6	2015-01-20	21.294 mi
Registration #7	2016-01-28	22.314 mi
Registration #8	2017-01-24	23.329 mi
Registration #9	2018-01-22	24.409 mi
Registration #10	2018-01-22	24.409 mi
Registration #11	2019-01-22	25.377 mi
Registration #12	2019-01-22	25.377 mi
Registration #13	2019-01-22	25.377 mi
Registration #14	2019-01-22	25.377 mi
Registration #15	2019-01-22	25.377 mi
Registration #16	2019-01-22	25.377 mi
Registration #17	2019-01-22	25.377 mi
Registration #18	2019-01-22	25.377 mi
Registration #19	2019-01-22	25.377 mi
Registration #20	2019-01-22	25.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1685 mm
Height	1349 mm
Length	3921 mm
Wheel base	2491 mm
Kerb weight	1160 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	19MH1865