



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA CLUB
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-09-02
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-18
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	4

MOT #15	2023-06-15 08:47
MOT test number	963429589261
Result	✓ Passed
Next expiry date	2024-06-18

MOT #14	2022-06-16 13:58
MOT test number	630490837882
Result	✓ Passed

MOT #13	2022-06-16 13:58
MOT test number	428483407381
Result	✗ Failed
Pass with rectification	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12**

2021-06-14 15:27

MOT test number

743453963370

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2020-06-19 14:47

MOT test number

718903091943

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10

2020-06-18 15:37

MOT test number

643606504765

Result

✗ Failed

MAJOR Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9** 2019-06-04 15:28**MOT test number** 401765398603**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect light misting (5.3.2 (b))**MOT #8** 2018-06-05 08:09**MOT test number** 292661330891**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2017-06-12 15:12**MOT test number** 490068708507**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage slightly distorted (2.4.G.1)**Advice** Exhaust corroded**MOT #6** 2016-05-20 13:48**MOT test number** 149887820108**Result** ✓ Passed**MOT #5** 2016-05-18 16:08**MOT test number** 961528374690**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside rear brake binding (3.7.B.1)



MOT #4	2015-05-18 16:20
--------	------------------

MOT test number	628568435119
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #3	2014-06-05 09:40
--------	------------------

MOT test number	245646754148
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2013-06-05 11:06
--------	------------------

MOT test number	499366753174
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2012-06-18 10:02
--------	------------------

MOT test number	786920372109
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 June 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YY59FMJ
Plate since	2020-06-29
Current registration	 YY59FMJ
Plate since	2020-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-30
Last registration	2023-06-15
Complete history	See info



Registration #1	2009-10-30	20 mi
Registration #2	2012-06-18	10.152 mi
Registration #3	2013-06-05	13.844 mi
Registration #4	2014-06-05	16.905 mi
Registration #5	2015-05-18	19.746 mi
Registration #6	2016-05-18	22.562 mi
Registration #7	2016-05-20	22.562 mi
Registration #8	2017-06-12	25.594 mi
Registration #9	2018-06-05	28.262 mi
Registration #10	2019-06-05	28.262 mi
Registration #11	2020-06-05	28.262 mi
Registration #12	2021-06-05	28.262 mi
Registration #13	2022-06-05	28.262 mi
Registration #14	2023-06-05	28.262 mi
Registration #15	2024-06-05	28.262 mi
Registration #16	2025-06-05	28.262 mi
Registration #17	2026-06-05	28.262 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1153344