





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	E-GOLF
Colour	White
Year of manufacture	2019
Top speed	93 mph
0 - 60 mph	9.6 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	290 Nm at 3.000 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 4

Date 2021-09-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 3

Date	2021-08-15

Pictures 40

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-08-15	
------	------------	--

Pictures 40

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date	2021-08-07
Date	2021 00 07
Pictures	0

CarCheck.co.uk page 2/11

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-03
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #3	2023-09-04 11:33
MOT test number	885417345623
Result	✓ Passed
Next expiry date	2024-09-03
Advice Nearside Front Body panel damaged and not likely to cause injury.	

MOT #2		2022-05-11 14:40
MOT test	number	544698679897
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

2022-05-10 15:04 **MOT #1** 257966888694 **MOT** test number Result × Failed **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail (5.2.3 (d) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Days left 126

MOT expiry date 3 September 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11




report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Correct registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-05-28
Last registration	2023-09-04
Complete history	See info



Registration #1	2019-05-28	20 mi
Registration #2		11.777 es
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

The VOLKSWAGEN factory car options list is only available in the premium report. S0225 Air conditioning S0295 S0482 S0501 S0566 S0567 S0569 View the complete VOLKSWAGEN factory list for this vehicle here.

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4349 mm
Wheel base	2629 mm
Kerb weight	1615 kg
Max. allowed weight	2020 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
CarChock co.uk	nago 11/1

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	EAZA022117