



report date: 2024-03-29

General information

Make	VAUXHALL
Model	TIGRA SXI AC 16V
Colour	Black
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	125 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-25
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #15</b>	2021-05-28 13:29
<b>MOT test number</b>	423946416753
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-06-01
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Rear both rear tyres slightly out of shape
<b>Advice</b>	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
<b>Advice</b>	Rear Brake pipe corroded, covered in grease or other material along tank (1.1.11 (c))

<b>MOT #14</b>	2021-05-28 09:32
<b>MOT test number</b>	134938030799
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Rear both rear tyres slightly out of shape
<b>Advice</b>	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Rear Brake pipe corroded, covered in grease or other material along tank (1.1.11 (c))

<b>MOT #13</b>	2020-06-02 15:25
<b>MOT test number</b>	342381473874
<b>Result</b>	✓ Passed

<b>MOT #12</b>	2020-06-02 09:48
<b>MOT test number</b>	788673161492
<b>Result</b>	✗ Failed
<b>Fail</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Fail</b>	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
<b>Fail</b>	Offside Brake cable damaged (1.1.15 (a))

**MOT #11** 2019-06-01 11:02**MOT test number** 664266920089**Result** ✓ Passed**MOT #10** 2018-06-01 10:32**MOT test number** 921045972052**Result** ✓ Passed**MOT #9** 2018-06-01 10:32**MOT test number** 381671120599**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #8** 2017-06-01 13:38**MOT test number** 918853828099**Result** ✓ Passed**MOT #7** 2017-06-01 07:45**MOT test number** 395218404376**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2016-06-02 07:37**MOT test number** 579465495932**Result** ✓ Passed**MOT #5** 2015-06-02 16:27**MOT test number** 918583955135**Result** ✓ Passed**Notice** Fuel filter corroded,

**MOT #4** 2014-05-20 12:48**MOT test number** 247500544481**Result** ✓ Passed**Notice** Nail in nearside front tyre**Notice** Coolant leak**MOT #3** 2013-05-02 12:19**MOT test number** 137742223180**Result** ✓ Passed**MOT #2** 2013-04-27 12:49**MOT test number** 256987913121**Result** ✗ Failed**Advice** Offside front brake grabbing slightly (3.7.A.2b)**Fail** Brake cable has restricted free movement (3.5.1k)**Notice** Nail in nearside rear tyre**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Nearside front brake grabbing slightly (3.7.A.2b)**Fail** Nearside Headlamp aim too far to the left (1.8)**Notice** Items removed from driver's view prior to test**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)



MOT #12012-04-28 13:36

MOT test number545929112183

Result

✓ Passed

Advice

Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Notice

Items removed from driver's view prior to test

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>SH09UAD</b>
Plate since	2019-03-29
Current registration	<b>SH09UAD</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-29
Last registration	2021-05-28
Complete history	<a href="#">See info</a>



Registration #1	2009-04-29	18 mi
Registration #2	2012-04-28	25.990 mi
Registration #3	2013-04-27	34.076 mi
Registration #4	2013-05-02	34.115 mi
Registration #5	2014-05-20	41.321 mi
Registration #6	2015-06-02	43.686 mi
Registration #7	2016-06-02	48.168 mi
Registration #8	2017-06-01	52.503 mi
Registration #9	2017-06-01	52.505 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi
Registration #17	2019-05-29	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1707 mm
Height	1494 mm
Length	3999 mm
Wheel base	2511 mm
Kerb weight	1102 kg
Max. allowed weight	1615 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	19SC2680