





report date: 2024-03-29

### General information

Make	MINI	
Model	COOPER AUTO COOPER	
Colour	Red	
Year of manufacture	2011	
Top speed	122 mph	
0 - 60 mph	9.1 seconds	
Gearbox	6 speed automatic	

## Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	150 g/km
CO2 label	F



CarCheck.co.uk page 1/10



## Internet history

Fn	trv	1
	ILI Y	-

Life y 1	
Date	2021-05-28
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2022-07-23
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #6	2021-06-30 16:31
MOT test number	935303236716
Result	<b>✓</b> Passed
Next expiry date	2022-07-23

MOT #5	2021-06-28 14:37
MOT test number	182520565019
Result	<b>×</b> Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #4	2020-07-24 13:46
MOT test number	304089679664
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside and nearside front road wheels slightly distorted	

CarCheck.co.uk page 3/10



YC61NZX

report date: 2024-03-29

MOT #3 2019-02-12 13:16

**MOT test number** 643426100215

**Result** ✓ Passed

Minor

Central Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #2 2017-06-23 09:15

**MOT test number** 192853496717

**Advice** Front both tyres worn on inner edges

MOT #1 2016-05-11 13:14

**MOT test number** 383683342776

**Result** ✓ Passed

**Advice** 

Nearside front tyre has cut but not deep enough to reach ply or cords

CarCheck.co.uk page 4/10



YC61NZX

report date: 2024-03-29

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e union mestery	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2011-10-31
Last registration	2021-06-30
Complete history	See info



Registration #1	2011-10-31	10 mi
Registration #2	2016-05-11	14.305 mi
Registration #3	2017-06-23	22.493 mi
Registration #4	2019-02-12	27.505 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		n.m.

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1105 kg
Max. allowed weight	1565 kg

## Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles CarCheck.co.uk	2 page 10/10