



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	White
Year of manufacture	2012
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-09-12
Pictures	29
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-04
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	13
Total items failed	19

MOT #16	2023-08-19 09:55
MOT test number	576594297262
Result	✓ Passed
Next expiry date	2024-09-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #15	2023-08-10 14:56
MOT test number	291613604563
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Fail	Nearside Rear Hydraulic brake calliper damaged and braking performance affected park brake lever seized on (1.1.16 (a) (ii))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

MOT #14	2022-08-19 15:20
MOT test number	265625574554
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view Chip in Screen (3.2 (a) (i))

**MOT #13** 2022-08-19 13:20**MOT test number** 579284513219**Result** ✗ Failed**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view Chip in Screen (3.2 (a) (i))**MOT #12** 2021-09-05 15:39**MOT test number** 235372357795**Result** ✓ Passed**MOT #11** 2021-08-27 12:14**MOT test number** 714032931143**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened bothsides (1.1.14 (a) (ii))**Fail** Offside Front Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened bothsides (1.1.14 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #10** 2019-07-11 15:45**MOT test number** 247003374077**Result** ✓ Passed

**MOT #9** 2019-07-09 13:07**MOT test number** 886123753838**Result** ✗ Failed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Headlamp aim not tested (4.1.2 (b))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**MOT #8** 2019-01-19 10:01**MOT test number** 607153531618**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-01-19 10:01**MOT test number** 545930412687**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #6** 2018-01-13 09:50**MOT test number** 887374435371**Result** ✓ Passed

**MOT #5** 2017-01-20 11:50**MOT test number** 442385750327**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2016-01-15 14:34**MOT test number** 227217622377**Result** ✓ Passed**MOT #3** 2016-01-15 09:27**MOT test number** 541792094360**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #2** 2015-01-21 12:01**MOT test number** 979071925083**Result** ✓ Passed**MOT #1** 2015-01-21 12:01**MOT test number** 226611925080**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
4 September 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-25
Last registration	2023-08-19
Complete history	See info



Registration #1	2012-01-25	29 mi
Registration #2	2015-01-21	14.259 mi
Registration #3	2016-01-15	19.843 mi
Registration #4	2016-01-15	19.843 mi
Registration #5	2017-01-20	27.602 mi
Registration #6	2018-01-13	49.197 mi
Registration #7	2019-01-19	67.488 mi
Registration #8	2019-01-19	67.488 mi
Registration #9	2019-07-09	73.917 mi
Registration #10	2019-07-09	73.917 mi
Registration #11	2019-07-09	73.917 mi
Registration #12	2019-07-09	73.917 mi
Registration #13	2019-07-09	73.917 mi
Registration #14	2019-07-09	73.917 mi
Registration #15	2019-07-09	73.917 mi
Registration #16	2019-07-09	73.917 mi
Registration #17	2019-07-09	73.917 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4

Number of axles	2
Engine number	G4FDBU724579