




report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Grey
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-07
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	27
Total items failed	10

MOT #11	2023-08-18 11:41
MOT test number	989119795709
Result	✓ Passed
Next expiry date	2024-08-22

MOT #10	2022-08-10 12:37
MOT test number	735187140376
Result	✓ Passed

MOT #9	2021-08-23 15:33
MOT test number	249580089098
Result	✓ Passed

MOT #8	2020-12-02 14:02
MOT test number	526147930520
Result	✓ Passed

- Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7**

2020-11-30 15:26

MOT test number

824847595879

Result**✗ Failed****Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Advice** Offside Rear Valve stem slightly damaged (5.2.3 (j))**Fail** Nearside Rear Reversing lamp inoperative (4.6.1 (a))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material slight corrosion (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Rear Reversing lamp inoperative (4.6.1 (a))



MOT #6	2019-12-05 16:45
MOT test number	444867219089
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both lipped (1.1.14 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Rear Brake pad(s) wearing thin close too limit (1.1.13 (a) (ii))
Advice	Front Tyre slightly damaged/cracking or perishing both have cuts & cracks (5.2.3 (d) (ii))
Advice	Nearside Rear Nail in tyre x 2

MOT #5	2018-12-06 16:42
MOT test number	781223617362
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front tyres have small cuts & cracks
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2018-12-06 14:53**MOT test number** 219282778969**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Front tyres have small cuts & cracks**Advice** Offside Front Nail in tyre**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2018-01-04 11:44**MOT test number** 574389090416**Result** ✓ Passed**Advice** Rear tailgate electrical wiring insecure slightly , but not likely to become damaged**Advice** Rear no plate slightly obscured , but still readable**MOT #2** 2017-01-10 12:51**MOT test number** 733133358354**Result** ✓ Passed**MOT #1** 2016-02-24 08:52**MOT test number** 971607459916**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	22 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 MA13GDX
Plate since	2019-03-29
Current registration	 MA13GDX
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-28
Last registration	2023-08-18
Complete history	See info



Registration #1	2013-03-28	23 mi
Registration #2	2016-02-24	18.306 mi
Registration #3	2017-01-10	19.757 mi
Registration #4	2018-01-04	26.119 mi
Registration #5	2018-12-06	31.995 mi
Registration #6	2018-12-06	31.995 mi
Registration #7	2019-12-05	39.040 mi
Registration #8	2019-12-05	39.040 mi
Registration #9	2019-12-05	39.040 mi
Registration #10	2019-12-05	39.040 mi
Registration #11	2019-12-05	39.040 mi
Registration #12	2019-12-05	39.040 mi
Registration #13	2019-12-05	39.040 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ