





report date: 2024-03-28

#### General information

Make	FIAT
Model	PANDA MULTIJET
Colour	Grey
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	60.1 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/11



# Internet history

#### Entry 1

Date 2021-07-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-05-23
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	16
Total items failed	1

MOT #4		2023-05-19 11:45
MOT test i	number	399925192894
Result		✓ Passed
Next expir	y date	2024-05-23
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #3		2022-05-20 14:53
MOT test	number	798544723984
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

2022-05-20 09:56 **MOT #2** 147643050413 **MOT test number** Result × Failed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b)) **Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #1	2021-05-14 14:10
MOT test number	430951574628
Result	✓ Passed

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	23 May 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \( \frac{1}{2} \)	
********	
***************************************	
************	
***************************************	
***************************************	
*************	
Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NIE AND LIKE
	UK C
Plate since	UK C

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-05-24
Last registration	2023-05-19
Complete history	See info



Registration #1	2018-05-24	11 mi
Registration #2	2021-05-14	16.881 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		71.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



## Dimensions & weight

Width	1882 mm
Height	1605 mm
Length	3686 mm
Wheel base	2300 mm
Kerb weight	1190 kg
Max. allowed weight	1595 kg

# Additional information

Fuel tank capacity	35 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	4 page :	11/11