





report date: 2024-03-28

General information

Make	FIAT
Model	500 C POP
Colour	Black
Year of manufacture	2011
Top speed	107 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	85 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	А



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-30

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-09
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	12
Total items failed	6

MOT #12	2024-04-10 15:32	
MOT test number	772499569303	
Result	✓ Passed	
Next expiry date	2025-04-09	
Advice Rear Suspension component mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Oil leak, but not excessive (8.4.1 (a) (i))		

MOT #11	2024-04-10 08:57
MOT test number	124096787583
Result	X Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Rear Suspension component mounting prescribed area is corroded but not all (5.3.6 (a) (i))	considered excessive

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

Result

Minor

Nearside Front Headlamp lens slightly defective cloudy (4.1.1 (b) (i))

Minor

Offside Front Headlamp lens slightly defective cloudy (4.1.1 (b) (i))

Advice

Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9

MOT test number

447391134615

Result

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Fail Exhaust emissions likely to be affected by an exhaust leak flexi section leaking (8.2.2.1 (b))

MOT #8	2021-09-29 20:15
MOT test number	540953881702
Result	✓ Passed
MOT #7	2021-03-15 15:56

MOT test number 183236752032

Result ✓ Passed

MOT #6 2020-03-12 11:59

MOT test number 165948273490

Result ✓ Passed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification

Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #4

MOT test number

119068754609

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #3 2018-01-08 16:07 **MOT** test number 326482936931 Result ✓ Passed **MOT #2** 2015-05-05 11:56 **MOT** test number 466115025118 Result ✓ Passed **MOT #1** 2014-07-31 14:33 **MOT** test number 399672114475 Result Passed

CarCheck.co.uk page 5/12



FY110HV report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



FY110HV report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e mier meerty	
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is	

Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NE ZIS
Plate since	
Current registration	NIE NIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



FY110HV report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-07-29
Last registration	2024-04-10
Complete history	See info



Registration #1	2011-07-29	9 mi
Registration #2	2014-07-31	67.214 mi
Registration #3	2015-05-05	71.640 mi
Registration #4	2018-01-08	77.047 mi
Registration #5	2019-03-13	78.280 mi
Registration #6	2020-03-12	82.015 mi
Registration #7	2020-03-12	82.015 mi
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		
Registration #12		
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	930 kg
Max. allowed weight	1370 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles2Engine number0012511