



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-20
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #19	2023-06-12 14:20
MOT test number	970453684732
Result	✓ Passed
Next expiry date	2024-06-15
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Advice Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive strut (5.3.6 (a) (i))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slightly perished/cracked (5.3.4 (a) (i))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #18	2023-06-08 13:40
MOT test number	955987675494
Result	✗ Failed
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slightly perished/cracked (5.3.4 (a) (i))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	
MAJOR Rear fog lamp not working (4.5.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive strut (5.3.6 (a) (i))	

MOT #17	2022-06-14 11:58
MOT test number	718195875160
Result	✓ Passed

Advice Nearside Front top sturt mount is knocking

Advice Various suspension braking and steering components have coroded

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1
(b) (i))

**MOT #16** 2021-06-16 15:26**MOT test number** 989203863101**Result** ✓ Passed**MOT #15** 2020-07-20 15:21**MOT test number** 532732272557**Result** ✓ Passed**MOT #14** 2020-07-20 11:30**MOT test number** 186900734190**Result** ✗ Failed**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Nearside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #13** 2019-04-20 10:52**MOT test number** 402144570595**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-04-18 09:51**MOT test number** 118490724501**Result** ✗ Failed**DANGEROUS** Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-04-17 10:38**MOT test number** 833639193436**Result** ✓ Passed**Advice** Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2017-04-19 08:31**MOT test number** 317879962415**Result** ✓ Passed**Advice** Offside Front Outer brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2016-05-20 10:03**MOT test number** 690172710791**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Both rear shocks have grease on them**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)

**MOT #8** 2015-05-28 09:42**MOT test number** 205208945496**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**MOT #7** 2014-05-19 14:49**MOT test number** 715099634134**Result** ✓ Passed**Advice** Offside Front coil spring corroded (2.4.C.1b)**MOT #6** 2013-05-13 09:15**MOT test number** 537923433155**Result** ✓ Passed**Notice** Exhaust tailbox in poor condition**Notice** Items removed from driver's view prior to test**MOT #5** 2013-05-13 09:15**MOT test number** 978223333163**Result** ✗ Failed**Notice** Exhaust tailbox in poor condition**Pass with rectification** Rear Rear fog lamp not working (1.3.2b)**Notice** Items removed from driver's view prior to test**MOT #4** 2012-05-14 11:02**MOT test number** 17775332183**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #3	2011-05-23 15:50
MOT test number	756243441194
Result	✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
Notice	Front discs scored on inner faces

MOT #2	2010-05-25 16:24
MOT test number	162275240113
Result	✓ Passed
Advice	Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1	2009-05-18 14:27
MOT test number	422388339134
Result	✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KU06CRX
Plate since	2024-03-29
Current registration	KU06CRX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-05-31
Last registration	2023-06-12
Complete history	See info



Registration #1	2006-05-31	13 mi
Registration #2	2009-05-18	8.845 mi
Registration #3	2010-05-25	10.531 mi
Registration #4	2011-05-23	12.876 mi
Registration #5	2012-05-14	15.027 mi
Registration #6	2013-05-13	16.897 mi
Registration #7	2014-05-19	19.723 mi
Registration #8	2015-05-28	21.619 mi
Registration #9	2016-05-20	23.035 mi
Registration #10	2017-04-19	24.040 mi
Registration #11	2018-05-20	25.277 mi
Registration #12	2019-05-20	26.277 mi
Registration #13	2020-05-20	27.277 mi
Registration #14	2021-05-20	28.277 mi
Registration #15	2022-05-20	29.277 mi
Registration #16	2023-05-20	30.277 mi
Registration #17	2024-05-20	31.277 mi
Registration #18	2025-05-20	32.277 mi
Registration #19	2026-05-20	33.277 mi
Registration #20	2027-05-20	34.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	FST65298536