





report date: 2024-03-29

General information

Make	PEUGEOT
Model	RCZ THP GT
Colour	White
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	240 Nm at 1.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-13

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history	M	OT	history
-------------	---	----	---------

MOT expiry date	2024-12-06
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	9

MOT #16	2023-12-07 10:14
MOT test number	653783827106
Result	✓ Passed
Next expiry date	2024-12-06

MOT #15	2022-12-07 11:48
MOT test number	686516010391
Result	✓ Passed

MOT #14		2022-12-07 11:48
MOT test number		674757845885
Result		X Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number
632213786637

Result

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge Right on the limit (5.2.3 (e))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge Right on the limit (5.2.3 (e))

MOT #12 2020-12-02 15:04 **MOT** test number 508178057076 Result ✓ Passed **MOT #11** 2020-11-27 11:14 143862781527 **MOT** test number Result × Failed Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) **Advice** Exhaust has a minor leak of exhaust gases from flexi section. (6.1.2 (a)) **Advice** Front Inner brake discs corroded.

MOT #10

MOT test number

192597442878

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice
Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice
Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice
Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))

MOT test number

Result

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

Result

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

S32201400605

Result

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Pass with rectification Offside Headlamp aim too high (1.8)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2016-02-02 14:56 **MOT** test number 825616903040 Result × Failed Pass with rectification Offside Front Headlamp not working on dipped beam fitted new bulb (1.7.5a) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) **Pass with rectification** Offside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc surecured (2.5.C.1a) **Pass with rectification** Front Windscreen washer provides insufficient washer liquid refilled (8.2.3) **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

667469014342

Result

✓ Passed

MOT test number

Result

Fail Nearside Rear Road wheel distorted (4.2.A.1a)

Fail Offside Rear Stop lamp not working (1.2.1b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #1 2013-12-13 15:46

MOT test number 395527343324

Result ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



DA60XWR report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

_	
Owner	hictory
OWITE	HIISLOLY

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-02-12
Last registration	2023-12-07
Complete history	See info



Registration #1	2011-02-12	17 mi
Registration #2	2013-12-13	22.715 mi
Registration #3	2014-11-08	32.010 mi
Registration #4	2014-11-15	32.010 mi
Registration #5	2016-02-02	43.496 mi
Registration #6	2016-02-02	43.496 mi
Registration #7	2017-01-25	47.109 mi
Registration #8	2017-01-25	47.109 mi
Registration #9	2018-01-04	51.406 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 au

More info >

CarCheck.co.uk page 13/14



DA60XWR report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2107 mm
Height	1352 mm
Length	4290 mm
Kerb weight	1350 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles CarCheck.co.uk	2 page 14/14

Engine number

FJBG1047469