



RENAULT

BD06EZN

report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC EXPRESSION VVT 111 SCENIC EU4
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 1

Date	2021-06-03
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #25** 2022-07-12 14:45**MOT test number** 920773085814**Result** ✓ Passed**Next expiry date** 2023-07-11**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**MOT #24** 2022-07-11 13:44**MOT test number** 931254816063**Result** ✗ Failed**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #23**

2022-06-13 10:11

MOT test number

126792108640

Result**✗ Failed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**DANGEROUS** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Minor** Windscreen wiper blade defective (3.4 (b) (i))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #22** 2021-06-04 10:46**MOT test number** 251916322937**Result** ✓ Passed

- Advice** Nearside wing mirror taped in place
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Centre exhaust heat shield loose
- Advice** Rear Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

MOT #21 2020-09-22 10:40**MOT test number** 781929426174**Result** ✓ Passed**MOT #20** 2020-09-22 10:40**MOT test number** 331461651097**Result** ✗ Failed

- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19 2019-09-20 07:52**MOT test number** 219169868857**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Valve stem slightly damaged both sides (5.2.3 (j))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rear pipes covered in grease (1.1.11 (c))

**MOT #18**

2019-09-17 10:23

MOT test number

634773182940

Result**✗ Failed**

Advice Brake pipe corroded, covered in grease or other material front to rear pipes covered in grease (1.1.11 (c))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Front Valve stem slightly damaged both sides (5.2.3 (j))

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #17

2018-09-27 11:03

MOT test number

428283472163

Result**✓ Passed**

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2018-09-24 10:28

MOT test number

281440371129

Result**✗ Failed**

- MAJOR** Nearside Front All direction indicators incorrect colour (4.4.3 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Rear All direction indicators incorrect colour (4.4.3 (a))
- MAJOR** Nearside Obligatory mirror insecure (3.3 (b) (ii))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front All direction indicators incorrect colour (4.4.3 (a))
- MAJOR** Offside Rear All direction indicators incorrect colour (4.4.3 (a))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #15

2017-10-16 09:33

MOT test number

344836701730

Result**✓ Passed**

- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Steering system has slight free play detected at steering wheel (2.2.A.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #14** 2016-10-28 14:28**MOT test number** 860303129473**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Play in steering rack inner joint(s)**MOT #13** 2015-11-02 12:34**MOT test number** 270161251704**Result** ✓ Passed**Advice** Rear not checked child seats in car**MOT #12** 2015-11-02 11:03**MOT test number** 681074151232**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Rear not checked child seats in car**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #11** 2014-10-23 08:55**MOT test number** 368516294226**Result** ✓ Passed**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**Notice** Play in steering rack inner joint(s)**Notice** Offside rear tyre perished

**MOT #10** 2013-10-31 12:05**MOT test number** 126464603392**Result** ✓ Passed**Notice** Wiper blade hitting scuttle plate**MOT #9** 2013-10-31 10:54**MOT test number** 139854803371**Result** ✗ Failed**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Notice** Wiper blade hitting scuttle plate**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #8** 2012-11-02 17:07**MOT test number** 105777902376**Result** ✓ Passed**Advice** Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)**MOT #7** 2012-11-02 17:07**MOT test number** 267977602389**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear Seat belt cut but webbing not significantly weakened (5.2.2a)**MOT #6** 2012-04-14 11:31**MOT test number** 405735602178**Result** ✓ Passed

**MOT #5** 2011-04-18 15:09**MOT test number** 465568601115**Result** ✓ Passed**MOT #4** 2011-04-18 10:41**MOT test number** 678718001138**Result** ✗ Failed**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Drag link end ball joint has excessive play (2.2.B.1f)**MOT #3** 2010-04-10 10:24**MOT test number** 411520900190**Result** ✗ Failed**Notice** Nail in offside rear tyre**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear wiper split**Notice** Nail in nearside rear tyre**Notice** Cut in offside front tyre sidewall**Pass with rectification** Nearside Headlamp not in good working order adversely affecting beam image (1.2.4a)**Notice** Front wipers lightly smearing screen**Notice** Front tyres worn on edges



MOT #2 2010-04-10 10:24

MOT test number 522320800187

Result ✓ Passed

- Notice** Nail in nearside rear tyre
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front wipers lightly smearing screen
- Notice** Cut in offside front tyre sidewall
- Notice** Front tyres worn on edges
- Notice** Nail in offside rear tyre
- Notice** Rear wiper split

MOT #1 2009-04-23 11:27

MOT test number 584753819121

Result ✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-05-31
Last registration	2022-07-12
Complete history	See info



Registration #1	2006-05-31	23 mi
Registration #2	2009-04-23	16.919 mi
Registration #3	2010-04-10	22.199 mi
Registration #4	2011-04-18	29.230 mi
Registration #5	2011-04-18	29.230 mi
Registration #6	2012-04-14	35.795 mi
Registration #7	2012-11-02	38.265 mi
Registration #8	2013-10-31	42.061 mi
Registration #9	2014-10-23	46.355 mi
Registration #10	2015-11-02	50.897 mi
Registration #11	2015-11-02	50.897 mi
Registration #12	2016-10-28	55.798 mi
Registration #13	2016-10-28	55.798 mi
Registration #14	2016-10-28	55.798 mi
Registration #15	2016-10-28	55.798 mi
Registration #16	2016-10-28	55.798 mi
Registration #17	2016-10-28	55.798 mi
Registration #18	2016-10-28	55.798 mi
Registration #19	2016-10-28	55.798 mi
Registration #20	2016-10-28	55.798 mi
Registration #21	2016-10-28	55.798 mi
Registration #22	2016-10-28	55.798 mi
Registration #23	2016-10-28	55.798 mi
Registration #24	2016-10-28	55.798 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1915 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D089414