





report date: 2024-03-29

General information

Make	VOLVO
Model	XC60 D4 MOMENTUM AWD
Colour	Grey
Year of manufacture	2018
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	2.8 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



GC18EEF

report date: 2024-03-29

Internet history

Entry 2

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-08-07
------	------------

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-28
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	1

	2023-08-29 10:22
number	957080252525
	✓ Passed
ry date	2024-08-28
Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Rear Brake disc worn, pitted or scored, but not seriously weaken Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #3	2022-08-01 14:08
MOT test number	577116884887
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2		2021-07-21 11:05
MOT test	number	765166410493
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



Result

GC18EF
report date: 2024-03-29

X Failed

MOT #1 2021-07-21 11:05

MOT test number 204662704874

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Front Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/11



GC18EEF

report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 September
Days left	125
MOT expiry date	28 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



furthe scinors

GC18EEF

report date: 2024-03-29

More info >

Owner history For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLVO had different number plates.

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-08-02
Last registration	2023-08-29
Complete history	See info



Registration #1	2018-08-02	12 mi
Registration #2	2021-07-21	33.080 mi
Registration #3	2021-07-21	33.080 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	87%
Pedestrian	76%
Safety systems	95%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1999 mm
Height	1658 mm
Length	4688 mm
Wheel base	2865 mm
Kerb weight	1837 kg
Max. allowed weight	2450 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2839783