



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	VIANO CDI LONG AMBIENTE
Colour	Silver
Year of manufacture	2006
Top speed	108 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	329 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	32.1 mpg
CO2 emission	232 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-11-18
Pictures	7
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2022-11-11
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	31
Total items failed	26

MOT #23 2021-11-12 12:33

MOT test number 797704229203

Result ✓ Passed

Next expiry date 2022-11-11

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))

MOT #22 2020-12-31 15:35

MOT test number 802191097946

Result ✓ Passed

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Under-trays fitted
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #21**

2019-12-27 08:49

**MOT test number**

103049205240

**Result**

✓ Passed

**Advice** Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Rear Oil leak, but not excessive diff (8.4.1 (a) (i))**Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #20**

2018-12-22 09:36

**MOT test number**

493718896771

**Result**

✓ Passed

**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #19**

2018-12-22 09:36

**MOT test number**

652961576023

**Result**

✗ Failed

**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #18**

2018-01-08 07:07

**MOT test number**

179267223715

**Result**

✓ Passed

**Advice** Offside Front Steering rack gaiter deteriorated (2.2.D.2d)**Advice** Factory fitted tinted side and rear windows

**MOT #17** 2018-01-08 07:07**MOT test number** 213022274218**Result** ✗ Failed**Advice** Factory fitted tinted side and rear windows**Pass with rectification** Brake pedal anti-slip provision worn smooth (3.3.A.1b)**Advice** Offside Front Steering rack gaiter deteriorated (2.2.D.2d)**MOT #16** 2017-01-03 07:03**MOT test number** 720126232032**Result** ✓ Passed**Advice** Factory fitted tinted side and rear windows**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #15** 2016-01-07 19:00**MOT test number** 464840054629**Result** ✓ Passed**MOT #14** 2015-12-14 17:07**MOT test number** 706619698576**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Front Inner Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)

**MOT #13** 2013-12-10 18:34**MOT test number** 975454643320**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2012-12-10 11:16**MOT test number** 246465642326**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**MOT #11** 2012-12-10 11:16**MOT test number** 658605842374**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

**MOT #10**

2012-09-25 16:37

**MOT test number**

997839962282

**Result****✗ Failed****Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #9**

2011-09-16 16:36

**MOT test number**

465979251208

**Result****✓ Passed****MOT #8**

2011-09-15 11:33

**MOT test number**

839558951276

**Result****✗ Failed****Pass with rectification** Nearside Headlamp aim too high (1.8)**Fail** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)**Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #7** 2010-08-16 16:34**MOT test number** 224798320283**Result** ✓ Passed**Advice** Steering column top bearing slightly worn (2.1.2c)**MOT #6** 2010-01-14 09:30**MOT test number** 102304310066**Result** ✓ Passed**MOT #5** 2010-01-12 12:54**MOT test number** 854542210085**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4** 2009-01-20 13:19**MOT test number** 534120129016**Result** ✓ Passed**MOT #3** 2008-04-14 14:21**MOT test number** 772845608173**Result** ✓ Passed**MOT #2** 2008-01-08 15:07**MOT test number** 853938408055**Result** ✓ Passed





MOT #1	2007-04-02 16:48
MOT test number	902732897047
Result	✓ Passed



Tax & MOT check

✕  
**Untaxed**

**Tax expired:**  
1 December 2022

✕  
**MOT**

**Expired:**  
11 November 2022

Tax status

Expired at 1 December 2022

Days left

514 days too late

MOT expiry date

11 November 2022

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-30
Last registration	2021-11-12
Complete history	<a href="#">See info</a>



Registration #1	2006-03-30	8 mi
Registration #2	2007-04-02	42.613 mi
Registration #3	2008-01-08	75.118 mi
Registration #4	2008-04-14	84.243 mi
Registration #5	2009-01-20	102.939 mi
Registration #6	2010-01-12	150.332 mi
Registration #7	2010-01-14	150.332 mi
Registration #8	2010-08-16	177.804 mi
Registration #9	2011-09-15	217.078 mi
Registration #10	2011-09-16	217.078 mi
Registration #11	2012-09-25	218.741 mi
Registration #12	2012-12-10	218.907 mi
Registration #13	2013-01-01	218.907 mi
Registration #14	2013-01-01	218.907 mi
Registration #15	2013-01-01	218.907 mi
Registration #16	2013-01-01	218.907 mi
Registration #17	2013-01-01	218.907 mi
Registration #18	2013-01-01	218.907 mi
Registration #19	2013-01-01	218.907 mi
Registration #20	2013-01-01	218.907 mi
Registration #21	2013-01-01	218.907 mi
Registration #22	2013-01-01	218.907 mi
Registration #23	2013-01-01	218.907 mi
Registration #24	2013-01-01	218.907 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1875 mm
Length	4993 mm
Wheel base	3200 mm
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8
Number of axles	2
Engine number	64698250198896