





report date: 2024-03-28

#### General information

Make	ТОУОТА
Model	AYGO VVT-I X-PLAY
Colour	Black
Year of manufacture	2018
Top speed	99 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	72 BHP
Max. torque	93 Nm at 4.400 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	57.6 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	A



CarCheck.co.uk page 1/11



## Internet history

#### Entry 1


Date 2021-06-04

Pictures 29

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-07-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	1

MOT #5		2023-07-06 11:42
MOT test	number	293667489271
Result		✓ Passed
Next expi	ry date	2024-07-09
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exces	sive movement (5.3.4 (a)
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exce	essive movement (5.3.4
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2023-07-06 11:42
MOT test number		623849302157
Result		<b>X</b> Failed
Advice Nearside Front S (a) (i))	Suspension arm pin or bush worn but not resulti	ng in excessive movement (5.3.4
Pass with rectification	Windscreen wiper does not clear the windscre	een effectively (3.4 (b) (ii))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Offside Rear Tyr	re worn close to legal limit/worn on edge (5.2.3	(e))

CarCheck.co.uk page 3/11



MOT test number

574545641920

Result

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing tread depth low (5.2.3 (d) (ii))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a))

(a) (i))	
MOT #2	2021-07-10 08:38
MOT test number	528345003761
Result	<b>✓</b> Passed
MOT #1	2021-01-24 11:24
MOT test number	582436427096
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	9 July 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r		)TA
********		
***************************************		
*************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-01-23
Last registration	2023-07-06
Complete history	See info



Registration #1	2018-01-23	16 mi
Registration #2	2021-01-24	25.871 mi
Registration #3		11.777 es
Registration #4	2021-07-10	27.531 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 mi

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	64%
Safety systems	57%
Overall rating	69%
Video	see crash video



# Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3455 mm
Wheel base	2340 mm
Kerb weight	855 kg
Max. allowed weight	1240 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	4 page 11/11