





General information

Make	VOLKSWAGEN
Model	GOLF SE TDI BLUEMOTION TECHNOLOGY
Colour	Black
Year of manufacture	2018
Top speed	123 mph
0 - 100 km/h	10.2 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	85 kW / 116 HP / 113 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	106 g/km
CO2 label	В







Internet history


Entry 3

Date Pictures 2021-07-23

27

Listing price

View report



source: yesauto.com

Entry 2	
Date	2021-07-14
Pictures	28
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-07-12
Pictures	28
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-03
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #5	2024-04-04 10:30	
MOT test number	719351268138	
Result	Passed	
Next expiry date	2025-04-03	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge Edge wearing. (5.2.3 (e))		

MOT #4		2023-03-27 09:38
MOT test	number	747853734862
Result		✓ Passed
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)
Advice	Front both tyres wearing on edges	

MOT #3		2022-03-31 14:49
MOT test	number	460830645428
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #2		2022-03-31 14:49
MOT test number		991443695976
Result		🗙 Failed
Advice Offside Front Sh	ock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Front Ty	re worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Headlamp aim projected beam image is	obviously incorrect (4.1.2 (c))
Advice Nearside Front	Tyre worn close to legal limit/worn on edge (5.2.3 (e	:))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))		

MOT #1	2021-03-25 09:20
MOT test number	599770584781
Result	✓ Passed



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 August 2024	Expires: 3 April 2025
Tax status	Valid until 1 August
Days left	93
MOT expiry date	3 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-03
Last registration	2024-04-04
Complete history	<u>See info</u>



Registration #1	2018-04-03	13 mi
Registration #2	2021-03-25	35.986 mi
Registration #3		11.777 est
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.117 mi

More info >





Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	2027 mm
Height	1492 mm
Length	4258 mm
Wheel base	2620 mm
Kerb weight	1223 kg
Additional information	

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
CarCheck.co.uk	page 11/11