



report date: 2024-03-28

General information

| | |
|---------------------|------------------|
| Make | FORD |
| Model | S-MAX ZETEC TDCI |
| Colour | Silver |
| Year of manufacture | 2007 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 138 BHP |
| Max. torque | 190 Nm at 4.500 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 52.3 mpg |
| Consumption combined | 44.1 mpg |
| CO2 emission | 169 g/km |
| CO2 label | H |





Internet history

Entry 2



| | |
|---------------|-----------------------------|
| Date | 2021-10-09 |
| Pictures | 12 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-19 |
| Pictures | 4 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-17 |
| MOT pass rate | 64 % |
| MOT passed | 14 |
| Failed MOT tests | 8 |
| Total advice items | 15 |
| Total items failed | 21 |

| | |
|------------------|--------------------------------------------------------------------|
| MOT #22 | 2023-11-18 11:14 |
| MOT test number | 172540907056 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-17 |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|-----------------|-----------------------------------------------------------------------|
| MOT #21 | 2023-11-16 16:22 |
| MOT test number | 785843795648 |
| Result | ✗ Failed |
| Fail | Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Fail | Front Windscreen washer provides insufficient washer liquid (3.5 (a)) |
| Advice | Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) |
| Fail | Offside Front Position lamp not working (4.2.1 (a) (ii)) |
| Fail | Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Advice | Front Oil leak, but not excessive (8.4.1 (a) (i)) |
| Fail | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |

**MOT #20** 2022-11-16 15:01**MOT test number** 853302179079**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #19** 2022-11-16 15:01**MOT test number** 955572786460**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))**Pass with rectification** Front Position lamp not working both (4.2.1 (a) (ii))**MOT #18** 2021-11-08 11:58**MOT test number** 401124727303**Result** ✓ Passed**MOT #17** 2020-10-06 13:26**MOT test number** 169565456555**Result** ✓ Passed**MOT #16** 2020-10-06 13:26**MOT test number** 507567420686**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))



| | |
|------------------------|------------------|
| MOT #15 | 2019-10-11 14:15 |
| MOT test number | 860781351517 |
| Result | ✓ Passed |

| | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|
| MOT #14 | 2019-10-10 08:24 |
| MOT test number | 981071967170 |
| Result | ✗ Failed |
| <div><div>Advice</div> Rear Brake disc worn, but not excessively (1.1.14 (a) (i))</div> <div><div>Fail</div> Service brake efficiency below requirements (1.2.2 (a) (i))</div> <div><div>Fail</div> Emissions not tested (8.2.2.2 (e))</div> <div><div>Fail</div> Nearside Front Service brake excessively fluctuating (1.2.1 (e))</div> <div><div>Fail</div> Front Windscreen washer not working (3.5 (a))</div> <div><div>Fail</div> Parking brake efficiency below requirements (1.4.2 (a) (i))</div> <div><div>Minor</div> Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))</div> <div><div>Fail</div> Rear Exhaust emissions likely to be affected by an exhaust leak (8.2.2.1 (b))</div> | |

| | |
|-------------------------------------------------------------------------------------------|------------------|
| MOT #13 | 2018-10-15 14:07 |
| MOT test number | 861483925639 |
| Result | ✓ Passed |
| <div><div>Advice</div> Exhaust has a minor leak of exhaust gases (6.1.2 (a))</div> | |

**MOT #12** 2018-10-15 14:07**MOT test number** 130530276571**Result** ✗ Failed**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**MOT #11** 2017-10-09 20:13**MOT test number** 331840354760**Result** ✓ Passed**MOT #10** 2016-10-21 08:30**MOT test number** 633388104316**Result** ✓ Passed**MOT #9** 2016-10-21 08:30**MOT test number** 477754464354**Result** ✗ Failed**Pass with rectification** Nearside Front Direction indicator incorrect colour (1.4.A.2f)**MOT #8** 2015-10-09 13:23**MOT test number** 731589436198**Result** ✓ Passed

**MOT #7** 2015-10-08 08:39**MOT test number** 780003102834**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #6** 2014-10-30 09:09**MOT test number** 715553904340**Result** ✓ Passed**MOT #5** 2013-10-02 16:51**MOT test number** 215575673216**Result** ✓ Passed**MOT #4** 2013-10-02 09:13**MOT test number** 359305073283**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #3** 2012-10-18 12:03**MOT test number** 538872292282**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-10-14 09:52**MOT test number** 277847381207**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #1 | 2010-10-11 11:02 |
| MOT test number | 542584480295 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
17 November 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 17 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|------------------------------------------------|------------|
| Vehicle class | 49 |
| Band | H |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-03-28 |
| Current registration | ***** |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 25 |
| First mileage registration | 2007-10-27 |
| Last registration | 2023-11-18 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-10-27 | 28 mi |
| Registration #2 | 2010-10-11 | 16.914 mi |
| Registration #3 | 2011-10-14 | 21.797 mi |
| Registration #4 | 2012-10-18 | 27.693 mi |
| Registration #5 | 2013-10-02 | 32.851 mi |
| Registration #6 | 2013-10-02 | 32.851 mi |
| Registration #7 | 2014-10-30 | 38.180 mi |
| Registration #8 | 2015-10-08 | 44.321 mi |
| Registration #9 | 2015-10-09 | 44.321 mi |
| Registration #10 | 2016-10-21 | 50.102 mi |
| Registration #11 | 2016-10-21 | 50.102 mi |
| Registration #12 | 2017-10-09 | 55.457 mi |
| Registration #13 | 2018-10-15 | 59.888 mi |
| Registration #14 | 2019-10-15 | 64.319 mi |
| Registration #15 | 2019-10-15 | 64.319 mi |
| Registration #16 | 2019-10-15 | 64.319 mi |
| Registration #17 | 2019-10-15 | 64.319 mi |
| Registration #18 | 2019-10-15 | 64.319 mi |
| Registration #19 | 2019-10-15 | 64.319 mi |
| Registration #20 | 2019-10-15 | 64.319 mi |
| Registration #21 | 2019-10-15 | 64.319 mi |
| Registration #22 | 2019-10-15 | 64.319 mi |
| Registration #23 | 2019-10-15 | 64.319 mi |
| Registration #24 | 2019-10-15 | 64.319 mi |
| Registration #25 | 2019-10-15 | 64.319 mi |



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1884 mm |
| Height | 1658 mm |
| Length | 4768 mm |
| Wheel base | 2850 mm |
| Kerb weight | 1736 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |

| | |
|---------------|---------|
| Engine number | 6R30967 |
|---------------|---------|