





report date: 2024-03-29

### General information

Make	CITROEN
Model	C4 PURETECH PLATINUM PICASSO
Colour	Blue
Year of manufacture	2016
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	205 Nm at 1.500 rpm
Engine capacity	1.200 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



**KP16SLU** 

report date: 2024-03-29

## Internet history

#### Entry 2

Date 2021-09-17

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 1

Date	2021-09-17
Pictures	9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-25
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	18
Total items failed	4

MOT #7		2023-09-26 11:12
MOT test	number	372785228703
Result		✓ Passed
Next expi	ry date	2024-09-25
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both o/	's and n/s (1.1.14 (a)
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3	3 (e))
Advice	Rear Brake pad(s) wearing thin both o/s and n/s close to 1.5mm limit change	ge asap (1.1.13 (a) (ii))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2	2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge close (5.2.3 (e))	

MOT #6	2022-09-26 14:42
MOT test number	235577663574
Result	✓ Passed
Advice Small oil leak	

MOT #5	2021-09-24 13:33
MOT test number	572870860744
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



KP16SLU

report date: 2024-03-29

MOT test number

608355300006

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

Advice Nearside Rear Nail in tyre

**MOT #3** 2020-03-18 12:23 **MOT test number** 802427914757 Result × Failed Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Advice Nearside Rear Nail in tyre Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) **Advice** Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e)) Pass with rectification Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #2		2019-04-11 10:46
MOT test n	number	166056113274
Result		✓ Passed
Minor	Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))	
Advice	Central Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Tyre worn close to legal limit/worn on edge both getting low (5.2.3 (e))	

CarCheck.co.uk page 4/12



MOT #1 2019-03-28 13:05

**MOT test number** 597358945117

Result X Failed

Advice Central Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Rear Fuel cap/sealing device ineffective (6.1.3 (b) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both getting low (5.2.3 (e))

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

CarCheck.co.uk page 5/12



Tax & MOT check





Expires: 25 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NK
Flate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-31
Last registration	2023-09-26
Complete history	See info



Registration #1	2016-03-31	6 mi
Registration #2	2019-03-28	25.974 mi
Registration #3	2019-04-11	25.974 mi
Registration #4	2020-03-18	31.316 mi
Registration #5	2020-03-18	31.316 mi
3		
Registration #6		11.77 m
		11.777 ea 11.777 ea
Registration #6		11.777 ea 11.777 ea 11.777 ea
Registration #6 Registration #7		71.77 es 71.77 es 71.77 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	***
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30396110

CarCheck.co.uk page 12/12