



NI7RWN

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER 90 TD5 XS STATION WAGON
Colour	Grey
Year of manufacture	2005
Top speed	111 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 1.950 rpm
Engine capacity	2.495 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	32.1 mpg
Consumption combined	28.2 mpg
CO2 emission	282 g/km
CO2 label	M






Internet history

Entry 2


Date	2023-02-17
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-23
Pictures	22
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	11
Total items failed	4

MOT #20 2024-01-17 14:34

MOT test number 309918049724

Result ✓ Passed

Next expiry date 2025-01-16

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #19 2022-10-25 14:33

MOT test number 960695985205

Result ✓ Passed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #18 2022-10-24 11:49

MOT test number 810945339099

Result ✗ Failed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**MOT #17** 2022-04-15 13:30**MOT test number** 726673620782**Result** ✓ Passed**MOT #16** 2020-09-10 09:45**MOT test number** 931274660064**Result** ✓ Passed**Advice** Steering box has seepage (2.1.1 (e) (i))**MOT #15** 2020-09-07 14:24**MOT test number** 342663759513**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Steering box has seepage (2.1.1 (e) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #14** 2019-05-23 09:40**MOT test number** 637771020627**Result** ✓ Passed**MOT #13** 2018-11-08 14:05**MOT test number** 145176662910**Result** ✓ Passed**MOT #12** 2017-11-02 14:59**MOT test number** 852095006571**Result** ✓ Passed

**MOT #11** 2017-11-01 17:19**MOT test number** 363628310491**Result** ✗ Failed**Fail** Offside Drag link end ball joint has excessive play (2.2.B.1f)**MOT #10** 2016-11-07 15:43**MOT test number** 831592373245**Result** ✓ Passed**MOT #9** 2015-11-11 15:48**MOT test number** 648252641772**Result** ✓ Passed**MOT #8** 2015-11-11 12:19**MOT test number** 118090027578**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2014-11-06 12:57**MOT test number** 276660214316**Result** ✓ Passed**MOT #6** 2013-10-31 10:00**MOT test number** 209664803378**Result** ✓ Passed**MOT #5** 2012-10-12 11:11**MOT test number** 148956882236**Result** ✓ Passed



MOT #4	2011-11-07 14:17
MOT test number	156801011313
Result	✓ Passed

MOT #3	2010-11-08 09:20
MOT test number	680082410391
Result	✓ Passed

MOT #2	2009-11-06 11:36
MOT test number	424570619448
Result	✓ Passed

MOT #1	2008-11-12 10:00
MOT test number	570617118352
Result	✓ Passed

Advice

Nearside Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-01
Last registration	2024-01-17
Complete history	See info



Registration #1	2005-09-01	21 mi
Registration #2	2008-11-12	20.277 mi
Registration #3	2009-11-06	28.205 mi
Registration #4	2010-11-08	32.145 mi
Registration #5	2011-11-07	35.173 mi
Registration #6	2012-10-12	37.489 mi
Registration #7	2013-10-31	41.823 mi
Registration #8	2014-11-06	47.836 mi
Registration #9	2015-11-11	51.763 mi
Registration #10	2015-11-11	51.763 mi
Registration #11	2016-11-07	57.094 mi
Registration #12	2017-11-01	62.113 mi
Registration #13	2018-11-01	65.277 mi
Registration #14	2019-11-01	68.277 mi
Registration #15	2020-11-01	71.277 mi
Registration #16	2021-11-01	74.277 mi
Registration #17	2022-11-01	77.277 mi
Registration #18	2023-11-01	80.277 mi
Registration #19	2024-01-17	83.277 mi
Registration #20	2024-01-17	86.277 mi
Registration #21	2024-01-17	89.277 mi
Registration #22	2024-01-17	92.277 mi
Registration #23	2024-01-17	95.277 mi

More info >



Dimensions & weight

Width	1790 mm
Height	1993 mm
Length	3883 mm
Wheel base	2360 mm
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of axles	2
Engine number	15P20426B