



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO VVT-I T SPIRIT
Colour	Blue
Year of manufacture	2011
Top speed	105 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	125 Nm at 4.000 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	58.9 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D








Internet history

Entry 1

Date	2021-05-23
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-12
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	38
Total items failed	6

MOT #142023-09-13 07:22

MOT test number161947502384

Result✓ Passed

Next expiry date2024-09-12

- Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice

Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice

Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2023-09-05 08:17

MOT test number

455612600373

Result**✗ Failed****Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12**

2022-09-02 10:55

MOT test number

234863565556

Result**✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11**

2021-08-06 11:50

MOT test number

152830479629

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #10

2020-08-25 09:48

MOT test number

176038308295

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2019-08-30 08:45

MOT test number

146113804390

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8

2018-08-29 16:29

MOT test number

769757057362

Result

✓ Passed

**MOT #7**

2018-08-29 09:03

MOT test number

801525837805

Result**✗ Failed****Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6**

2017-08-29 14:01

MOT test number

272308046325

Result**✓ Passed****MOT #5**

2017-08-29 12:52

MOT test number

519079829002

Result**✗ Failed****Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #4**

2016-08-31 08:34

MOT test number

423385773130

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)



MOT #3	2015-08-26 12:21
MOT test number	599031785993
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #2	2014-08-27 15:19
MOT test number	146549234299
Result	✓ Passed

MOT #1	2014-08-27 15:19
MOT test number	809989134221
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low and too far to the left. (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	12 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YX61OYS
Plate since	2019-03-29
Current registration	YX61OYS
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-01
Last registration	2023-09-13
Complete history	See info



Registration #1	2011-09-01	13 mi
Registration #2	2014-08-27	14.042 mi
Registration #3	2015-08-26	17.464 mi
Registration #4	2016-08-31	24.079 mi
Registration #5	2017-08-29	36.708 mi
Registration #6	2017-08-29	36.708 mi
Registration #7	2018-08-29	47.329 mi
Registration #8	2018-08-29	47.329 mi
Registration #9	2019-08-29	58.950 mi
Registration #10	2019-08-29	58.950 mi
Registration #11	2019-08-29	58.950 mi
Registration #12	2019-08-29	58.950 mi
Registration #13	2019-08-29	58.950 mi
Registration #14	2019-08-29	58.950 mi
Registration #15	2019-08-29	58.950 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1595 mm
Length	3990 mm
Wheel base	2550 mm
Kerb weight	1135 kg
Max. allowed weight	1545 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NR8026874