



 **BL06BXC**

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS C-MAX ZETEC
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg





Internet history

Entry 1

Date	2021-06-22
Pictures	1
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #19	2022-06-24 10:17
MOT test number	162418457437
Result	✓ Passed
Next expiry date	2023-06-27
Advice	Under vehicle / all steering + suspension components corroded
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18	2022-06-24 08:20
MOT test number	925584795617
Result	✗ Failed
Advice	Under vehicle / all steering + suspension components corroded
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect headlamp lens cloudy (4.1.2 (c))

MOT #17	2021-06-28 15:09
MOT test number	692118651483
Result	✓ Passed

MOT #16	2020-11-07 14:41
MOT test number	351031322343
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Power steering component has slight seepage from a component steering rack (2.1.5 (a))
Advice	Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a) (ii))

**MOT #15**

2019-11-09 09:25

MOT test number

286102098361

Result

✓ Passed

- Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Nearside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Advice** Power steering component has slight seepage from a component Steering rack (2.1.5 (a))

MOT #14

2018-11-10 11:54

MOT test number

483966613787

Result

✓ Passed

- Advice** Offside Front tyre wearing uneven.
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Valve stem slightly damaged both. (5.2.3 (j))
- Advice** Rear Coil spring corroded both. (5.3.1 (b) (i))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arms main bushes. (5.3.4 (a) (i))

**MOT #13** 2018-11-10 09:38**MOT test number** 994028422781**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush. (5.3.4 (a) (i))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arms main bushes. (5.3.4 (a) (i))**Advice** Offside Front tyre wearing uneven.**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush. (5.3.4 (a) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Coil spring corroded both. (5.3.1 (b) (i))**Advice** Front Valve stem slightly damaged both. (5.2.3 (j))**MOT #12** 2017-11-18 09:29**MOT test number** 615182161540**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**MOT #11** 2016-11-19 09:29**MOT test number** 214401049872**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2015-12-05 09:26**MOT test number** 417920428139**Result** ✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Child seat fitted to nearside rear not allowing a full inspection of the adult seatbelt

MOT #9 2015-01-08 14:39**MOT test number** 127298805479**Result** ✓ Passed**MOT #8** 2014-05-02 16:41**MOT test number** 457632624115**Result** ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

MOT #7 2014-04-28 10:41**MOT test number** 308568314105**Result** ✗ Failed

Fail Centre Rear Passenger's seat insecure (6.2.A.1)

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Fuel cap/sealing device does not fasten securely by positive means (7.2.4b)

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #6** 2013-04-25 10:25**MOT test number** 857735613151**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-04-30 16:37**MOT test number** 707281422179**Result** ✓ Passed**MOT #4** 2011-07-18 10:32**MOT test number** 946519891167**Result** ✓ Passed**MOT #3** 2010-07-12 09:19**MOT test number** 731883390194**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Leak from air conditioning condensor**MOT #2** 2009-07-14 16:29**MOT test number** 191015399107**Result** ✓ Passed**MOT #1** 2009-07-14 14:32**MOT test number** 202635399436**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	BL06BXC
Plate since	2024-03-29
Current registration	BL06BXC
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-07-20
Last registration	2022-06-24
Complete history	See info



Registration #1	2006-07-20	28 mi
Registration #2	2009-07-14	27.221 mi
Registration #3	2009-07-14	27.221 mi
Registration #4	2010-07-12	35.213 mi
Registration #5	2011-07-18	44.565 mi
Registration #6	2012-04-30	50.513 mi
Registration #7	2013-04-25	54.021 mi
Registration #8	2014-04-28	57.433 mi
Registration #9	2014-05-02	57.478 mi
Registration #10	2015-01-08	59.719 mi
Registration #11	2015-12-05	64.373 mi
Registration #12	2016-01-01	65.000 mi
Registration #13	2016-01-01	65.000 mi
Registration #14	2016-01-01	65.000 mi
Registration #15	2016-01-01	65.000 mi
Registration #16	2016-01-01	65.000 mi
Registration #17	2016-01-01	65.000 mi
Registration #18	2016-01-01	65.000 mi
Registration #19	2016-01-01	65.000 mi
Registration #20	2016-01-01	65.000 mi
Registration #21	2016-01-01	65.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1371 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6L08000