





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 SE BLUE DRIVE
Colour	White
Year of manufacture	2016
Top speed	104 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 4

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #7		2023-10-10 16:00
MOT test	number	942183981294
Result		✓ Passed
Next expi	ry date	2024-10-09
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on edges. (5.2.3 (e))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges. (5.2.3	(e))

MOT #6		2023-10-10 14:35
MOT test i	number	493453703754
Result		🗙 Failed
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Worn on edges. (5.2.	3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Worn on edges. (5.2.3	(e))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2022-10-07 08:58

MOT test number 490452664192

MOT #4 2022-10-05 15:53

MOT test number 592425963263

Result X Failed

DANGEROUS Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Windscreen washer not working (3.5 (a))

MOT #3 2021-06-12 09:24

MOT test number 695090451368

Result \rightarrow Passed

MOT #2 2020-06-26 16:21

MOT test number 458457926628

Result
✓ Passed

Advice Offside Front Brake disc worn, but not excessively slightly (1.1.14 (a) (i))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, but not excessively slightly (1.1.14 (a) (i))

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2019-06-26 08:34

MOT test number 439491062747

Result
✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	367
MOT expiry date	9 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

O		biote	- 100
· Ow	ne e	histo	иν

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
HARMAN CONTRACTOR CONT	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	NIEZ ZIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-06-30
Last registration	2023-10-10
Complete history	See info



Registration #1	2016-06-30	6 mi
Registration #2	2019-06-26	15.922 mi
Registration #3	2020-06-26	21.183 mi
Registration #4		11.777 es
Registration #5	2021-06-12	21.778 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4120 mm
Wheel base	2615 mm
Kerb weight	1267 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number G4FAFZ607182