





report date: 2024-03-29

## General information

Make	NISSAN
Model	MICRA ACENTA
Colour	Blue
Year of manufacture	2017
Top speed	98 mph
0 - 60 mph	16.4 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	70 BHP	
Max. torque	95 Nm at 3.500 rpm	
Engine capacity	999 сс	
Cylinders	3	
Fuel type	Petrol	
Consumption city	46.3 mpg	
Consumption extra urban	68.9 mpg	
Consumption combined	58.9 mpg	
CO2 emission	103 g/km	
CO2 label	В	



CarCheck.co.uk page 1/11



FH17VUM

report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-14
MOT pass rate	100 %
MOT passed	6
Failed MOT tests	0
Total advice items	17
Total items failed	0

MOT #6	2024-04-15 16:42	
MOT test number	312266017192	
Result	✓ Passed	
Next expiry date 2025-04-1		
Advice Front Suspension arm pin or bush worn but not resulting in excessive movement both front suspension rear bushes (5.3.4 (a) (i))		
Advice Front Suspension rod pin or bush worn but not resulting in excessive movement Both front suspension front bushes (5.3.4 (a) (i))		

MOT #5		2023-04-11 09:07	
MOT test	number	652038260264	
Result		✓ Passed	
Advice	Rear Service brake fluctuating, but not excessively both rear slight (1.2.1 (e))		
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracked in tread (5.2.	3 (d) (ii))	
Minor	Nearside Front Windscreen wiper blade defective blade split/ splitting at end of b	plade (3.4 (b) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracked in tread (5.2.3	3 (d) (ii))	
Advice	Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front and rear bushes (5.3.4 (a) (i))		
	ες (3.3.4 (α) (1))		
Advice	Nearside Front Tyre slightly damaged/cracking or perishing cracked in tread (5.	2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracked in tread (5.2	2.3 (d) (ii))	
Advice and rear l	Nearside Front Suspension arm pin or bush worn but not resulting in excessive bushes (5.3.4 (a) (i))	movement front	

CarCheck.co.uk page 3/11



MOT #4 2022-04-11 13:53

**MOT test number** 656531451527

**Result** ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing slightly cracking (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing slight cracking (5.2.3 (d) (ii))

Minor Nearside Front Windscreen wiper blade defective end of blade slightly split (3.4 (b) (i))

**Advice** Offside Front Play in steering rack inner joint(s) slight

Advice Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

MOT #3 2021-04-14 08:01

**MOT test number** 624916173180

Result \( \sqrt{Passed} \)

MOT #2 2020-10-13 10:10

**MOT test number** 594011543075

Result \( \sqrt{Passed} \)

**MOT #1** 2020-06-21 05:24

**MOT test number** 416614271051

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	14 April 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



FH17VUM

report date: 2024-03-29

### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		ιN
***************************************		
HARMAN CO. C.		
***************************************		
	More info	>
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	NK NA	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



FH17VUM

report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-29
Last registration	2024-04-15
Complete history	See info



Registration #1	2017-06-29	23 mi
Registration #2	2020-10-13	14.895 mi
Registration #3		11.777 es
Registration #4	2021-04-14	15.372 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 mi

More info >

CarCheck.co.uk page 10/11



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
S0566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	91%
Children	79%
Pedestrian	79%
Safety systems	72%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1743 mm
Height	1455 mm
Length	3999 mm
Wheel base	2525 mm
Kerb weight	1037 kg
Max. allowed weight	1490 kg

# Additional information

Fuel tank capacity	41
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11