



NA08NJK

report date: 2024-03-29

General information

Make	FORD
Model	FUSION STYLE CLIMATE
Colour	Black
Year of manufacture	-
Top speed	102 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg





Internet history

Entry 1	
Date	2021-07-23
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #14</b>	2021-05-28 10:32
<b>MOT test number</b>	526448129894
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-05-27

<b>MOT #13</b>	2021-05-28 10:32
<b>MOT test number</b>	800951465990
<b>Result</b>	✗ Failed

- Pass with rectification** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Pass with rectification** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

<b>MOT #12</b>	2019-10-31 17:32
<b>MOT test number</b>	845205920212
<b>Result</b>	✓ Passed

- Advice** Front Brake hose has slight corrosion to ferrule All ferrules (1.1.12 (f) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #11</b>	2019-10-29 12:43
<b>MOT test number</b>	476109431919
<b>Result</b>	✗ Failed

**Advice** Nearside Front Brake pipe hose not fully secured but not likely to become detached

**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Central Rear Seat belt retracting mechanism defective (7.1.2 (e))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Brake hose has slight corrosion to ferrule All ferrules (1.1.12 (f) (i))

**MOT #10** 2018-07-03 08:39**MOT test number** 844308555929**Result** ✓ Passed**MOT #9** 2017-06-30 14:16**MOT test number** 627180852621**Result** ✓ Passed**MOT #8** 2017-06-30 11:56**MOT test number** 342835483347**Result** ✗ Failed**Fail** Power steering malfunctioning (2.3.3a)**MOT #7** 2016-07-20 14:28**MOT test number** 884817570945**Result** ✓ Passed**Advice** All four tyres are cracking between treads**Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2016-03-23 12:47**MOT test number** 827628144701**Result** ✓ Passed**MOT #5** 2015-03-07 08:50**MOT test number** 116526565454**Result** ✓ Passed**MOT #4** 2014-03-28 11:09**MOT test number** 948587384079**Result** ✓ Passed



MOT #3 2013-03-18 12:16

MOT test number 169707173056

Result ✓ Passed

MOT #2 2012-03-12 12:12

MOT test number 848722172087

Result ✓ Passed

- Notice** Both rear tyre treads worn to 2mm on edges .
- Notice** Front brake discs corroded on inner faces .
- Notice** N/s/f tyre tread worn to 2mm on edge , sidewall scuffed .

MOT #1 2011-03-28 12:00

MOT test number 946067681090

Result ✓ Passed

- Notice** Ridge of corrosion on front discs



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-04-02
Last registration	2021-05-28
Complete history	<a href="#">See info</a>



Registration #1	2008-04-02	23 mi
Registration #2	2011-03-28	45.799 mi
Registration #3	2012-03-12	51.694 mi
Registration #4	2013-03-18	57.974 mi
Registration #5	2014-03-28	62.358 mi
Registration #6	2015-03-07	64.000 mi
Registration #7	2016-03-23	64.721 mi
Registration #8	2016-07-20	64.825 mi
Registration #9	2016-10-20	65.000 mi
Registration #10	2017-03-20	65.000 mi
Registration #11	2017-06-20	65.000 mi
Registration #12	2017-09-20	65.000 mi
Registration #13	2017-12-20	65.000 mi
Registration #14	2018-03-20	65.000 mi
Registration #15	2018-06-20	65.000 mi
Registration #16	2018-09-20	65.000 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1199 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8A48618