



KJI5XXW

report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 SE-L NAV
Colour	White
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	150 Nm at 4.800 rpm
Engine capacity	1.496 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	15
Total items failed	8

MOT #9	2024-04-09 11:06
MOT test number	599609501895
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #8	2023-04-05 15:37
MOT test number	973735596248
Result	✓ Passed
Advice	Offside Front Outer Brake pipe corroded, covered in grease or other material on bend (1.1.11 (c))

**MOT #7**

2023-03-31 07:33

MOT test number

652052849719

Result**✗ Failed**

- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Inner Brake disc significantly and obviously worn face reduced (1.1.14 (a) (i))
- Fail** Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Outer Brake pipe corroded, covered in grease or other material on bend (1.1.11 (c))
- Fail** Offside Front Outer Tyre has a tear, caused by separation or partial failure of its structure cracked down to cords (5.2.3 (d) (ii))

MOT #6

2022-04-06 11:06

MOT test number

306879115332

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

2022-04-06 08:17

MOT test number

334537752872

Result**✗ Failed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

**MOT #4** 2021-04-12 14:36**MOT test number** 512750616795**Result** ✓ Passed**MOT #3** 2020-08-19 11:34**MOT test number** 367189285647**Result** ✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Slightly corroded (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing Also worn slightly on outer edge (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing Also worn slightly on outer edge (5.2.3 (d) (ii))

MOT #2 2019-08-01 13:31**MOT test number** 393173053693**Result** ✓ Passed**MOT #1** 2018-08-17 13:15**MOT test number** 140069681900**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 April
Days left	336
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	KJ15XXW
Plate since	2015-03-29
Current registration	KJ15XXW
Plate since	2015-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-08-20
Last registration	2024-04-09
Complete history	See info



Registration #1	2015-08-20	21 mi
Registration #2	2018-08-17	11.004 mi
Registration #3	2019-08-01	13.383 mi
Registration #4	2020-08-19	19.880 mi
Registration #5	2021-04-12	21.477 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1225 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	975 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	P5 30214321