





General information

Make	VOLKSWAGEN
Model	PASSAT S TDI BLUEMOTION TECHNOLOGY
Colour	Blue
Year of manufacture	2015
Top speed	127 mph
0 - 100 km/h	11.0 seconds
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 kW / 120 HP / 118 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.3 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	В







Internet history

Entry 2	
Date	2022-06-24
Pictures	29
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-07-06
Pictures	50
Listing price	View report



source: cargurus.co.uk









MOT history

MOT expiry date	2024-06-30
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	2

MOT #8	2023-06-22 13:07
MOT test number	720527541746
Result	✓ Passed
Next expiry date	2024-06-30

MOT #7	2022-07-01 10:52
MOT test number	353796635797
Result	✓ Passed

MOT #6 2022	-06-24 07:35
MOT test number 71	3703597262
Result	🗙 Failed
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))





MOT #5		2021-10-16 09:08
MOT test	number	228103474238
Result		✓ Passed
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Nail in tyre o/s/f & n/s/r	

MOT #4

2021-01-26 13:48

MOT test number	729346946613
Result	✓ Passed

МОТ #3	2020-01-21 12:27
MOT test number	653398980159
Result	✓ Passed
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

MOT #2	2019-01-23 16:04
MOT test number	850762498023
Result	✓ Passed

MOT #1		2018-03-09 16:51
MOT test	number	516071472234
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

Tax due: 1 July 2024	✓ Taxed	Expires: 30 June 2024	√ мот
Tax status			Valid until 1 July
Days left			62
MOT expiry date			30 June 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 =

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-20
Last registration	2023-06-22
Complete history	See info



Registration #1	2015-03-20	24 mi
Registration #2	2018-03-09	48.809 mi
Registration #3	2019-01-23	58.554 mi
Registration #4	2020-01-21	76.448 mi
Registration #5	2021-01-26	90.101 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi

More info \rightarrow





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight		
Width	1820 mm	
Height	1516 mm	
Length	4771 mm	
Wheel base	2712 mm	
Kerb weight	1400 kg	
Max. allowed weight	2060 kg	
Additional information		
Fuel tank capacity	59	
Fuel delivery	Direct Injection	
Number of doors	5	
CarCheck.co.uk	page 1	1/11

Number of axles	2
Engine number	DCXA009039