

Ø



General information

| MakeLEXUSModelNX 300H F SPORTColourRedYear of manufacture2018Top speed112 mph0 - 60 mph9.2 secondsGearbox1 speed CVT | | |
|--|---------------------|-----------------|
| ColourRedYear of manufacture2018Top speed112 mph0 - 60 mph9.2 seconds | Make | LEXUS |
| Year of manufacture 2018 Top speed 112 mph 0 - 60 mph 9.2 seconds | Model | NX 300H F SPORT |
| Top speed 112 mph 0 - 60 mph 9.2 seconds | Colour | Red |
| 0 - 60 mph 9.2 seconds | Year of manufacture | 2018 |
| | Top speed | 112 mph |
| Gearbox 1 speed CVT | 0 - 60 mph | 9.2 seconds |
| | Gearbox | 1 speed CVT |

Engine & fuel consumption

| Power | 194 BHP |
|-------------------------|---------------------|
| Max. torque | 480 Nm at 4.200 rpm |
| Engine capacity | 2.494 сс |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 121 g/km |
| CO2 label | D |







Internet history


| Entry | 2 |
|-------|---|
| | |

Date Pictures 2021-07-02

19

Listing price

View report



source: heycar.co.uk

| Entry 1 | |
|---------------|-------------|
| Date | 2021-06-19 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-07-16 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #5 | 2023-07-14 11:16 |
|--|------------------|
| MOT test number | 847437597824 |
| Result | 🗸 Passed |
| Next expiry date 2024-07- | |
| Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt | |

| МОТ #4 | 2022-07-15 13:09 |
|-----------------|------------------|
| MOT test number | 705354067294 |
| Result | ✓ Passed |

| MOT #3 | 2021-07-17 08:24 |
|-----------------|------------------|
| MOT test number | 773369377732 |
| Result | ✓ Passed |

| MOT #2 | | 2021-01-21 13:08 |
|----------|--|------------------|
| MOT test | number | 121983165752 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |





| MOT #1 | 2021-01-21 13:08 | |
|---|---------------------------|--|
| MOT test number | 383481154687 | |
| Result | 🗙 Failed | |
| Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Pass with rectification Tyre pressure monitoring system malfunctioning or obvious | iously inoperative (5.2.3 | |
| (h)) | | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | | |



Tax & MOT check

| √ Taxed | ✓ MOT |
|-------------------------|--------------------------|
| Tax due: 1 July 2024 | Expires: 16 July 2024 |
| Tax status | Valid until 1 July |
| Days left | 64 |
| MOT expiry date | 16 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 59 |
|-------------------------------|------------|
| Band | G |
| First licence fee (12 months) | £ 200,00,- |
| Standard rate (12 months) | £ 170,00,- |
| Standard rate (6 months) | £ 93,50,- |
| Premium rate (12 months) | £ 560,00,- |
| Premium rate (6 months) | £ 308,00,- |





Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FEIDO |
| Category | AMP |
| Туре | K K |
| Damage 2 | AMPLE |
| Damage 2 | e et - |
| Date | S. |
| Category | AMPT |
| Туре | |

Extra LEXUS salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 = |





Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| ************ | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this LEXUS had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2018-02-13 |
| Last registration | 2023-07-14 |
| Complete history | See info |



| Registration #1 | 2018-02-13 | 14 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-01-21 | 67.317 mi |
| Registration #3 | 2021-01-21 | 67.317 mi |
| Registration #4 | | 11.777 esi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 82% |
| Children | 82% |
| Pedestrian | 69% |
| Safety systems | 71% |
| Overall rating | 77% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1845 mm |
| Height | 1645 mm |
| Length | 4640 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1785 kg |
| Max. allowed weight | 2395 kg |
| Additional information | |
| Fuel tank capacity | 56 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | 2AR1884772 |