



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D3 R-DESIGN
Colour	Red
Year of manufacture	2015
Top speed	127 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-15
Pictures	34
Listing price	View report



source: yesauto.com

**MOT history**

MOT expiry date	2024-06-24
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	9
Total items failed	2

MOT #8	2023-06-20 07:59
MOT test number	299668021669
Result	✓ Passed
Next expiry date	2024-06-24
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7	2022-06-22 14:55
MOT test number	823892252681
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
Advice	Engine x under covers fitted /

MOT #6	2021-06-25 15:54
MOT test number	537589998218
Result	✓ Passed

**MOT #5** 2020-09-14 14:44**MOT test number** 402875175863**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Cracked (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge At 3.5mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Cracked (5.2.3 (d) (ii))**MOT #4** 2020-03-04 09:20**MOT test number** 106743374052**Result** ✓ Passed**MOT #3** 2019-04-02 16:24**MOT test number** 577806954140**Result** ✓ Passed**Minor** Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**MOT #2** 2019-04-02 13:59**MOT test number** 304000377736**Result** ✗ Failed**Minor** Other passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**Fail** Undertray likely to become detached (6.2.1 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #1** 2018-03-20 16:05**MOT test number** 319587277377**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 June 2023

✓

MOT

Expires:
24 June 2024

Tax status	Expired at 1 June 2023
Days left	334 days too late
MOT expiry date	24 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KV64ZRZ
Plate since	2024-03-29
Current registration	KV64ZRZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-30
Last registration	2023-06-20
Complete history	See info



Registration #1	2015-01-30	21 mi
Registration #2	2018-03-20	14.807 mi
Registration #3	2019-04-02	18.370 mi
Registration #4	2019-04-02	18.370 mi
Registration #5	2020-03-04	20.789 mi
Registration #6	2020-03-04	20.789 mi
Registration #7	2020-03-04	20.789 mi
Registration #8	2020-03-04	20.789 mi
Registration #9	2020-03-04	20.789 mi
Registration #10	2020-03-04	20.789 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1488 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1384920