



KM64YNX


report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Black
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-03-04
Pictures	3
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-06-25
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	22
Total items failed	23

MOT #13	2023-06-26 15:03
MOT test number	579027146230
Result	✓ Passed
Next expiry date	2024-06-25
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer wall. (5.2.3 (d) (ii))
Advice	Nearside Rear Nail in tyre
Advice	Rear Exhaust mounting defective (6.1.2 (a))

**MOT #12**

2023-06-21 10:44

MOT test number

242449156313

Result**✗ Failed**

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most. (5.3.4 (a) (i))

Fail Nearside Rear Service brake excessively binding (1.2.1 (f))

Advice Nearside Rear Nail in tyre

Fail Offside Front Macpherson strut has an unsafe modification strut not fitted correctly. (5.3.3 (c) (i))

Advice Rear Exhaust mounting defective (6.1.2 (a))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Upper Macpherson strut top bush or bearing has excessive wear or free play top mount bearing. (5.3.4 (a) (i))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Tyre slightly damaged/cracking or perishing outer wall. (5.2.3 (d) (ii))

MOT #11

2022-06-24 10:45

MOT test number

141849619128

Result**✓ Passed**

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Exhaust mounting defective (6.1.2 (a))

**MOT #10**

2022-06-21 11:31

MOT test number

619389641502

Result**✗ Failed**

- Fail** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear rear exhaust heat shield insecure over rear silencer
- Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))

MOT #9

2021-03-31 10:19

MOT test number

329336743424

Result**✓ Passed****MOT #8**

2021-03-29 12:09

MOT test number

547286883377

Result**✗ Failed**

- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #7** 2020-12-16 16:43**MOT test number** 603439332230**Result** ✓ Passed**MOT #6** 2020-12-12 11:34**MOT test number** 343008630148**Result** ✗ Failed**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Offside Front Brake disc contaminated (1.1.14 (b))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Brake disc contaminated (1.1.14 (b))**MOT #5** 2019-10-29 16:51**MOT test number** 381414054677**Result** ✓ Passed**MOT #4** 2019-10-22 14:52**MOT test number** 612760451510**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Oil leaking excessively from transmission driveshaft seal (8.4.1 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #3** 2018-10-24 11:01**MOT test number** 722851277241**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Offside Oil leak, but not excessive Oil leak from driveshaft seal. (8.4.1 (a) (i))**MOT #2** 2018-10-24 08:17**MOT test number** 928220044324**Result** ✗ Failed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Oil leak, but not excessive Oil leak from driveshaft seal. (8.4.1 (a) (i))**MOT #1** 2017-10-05 12:04**MOT test number** 448005979275**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
25 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	25 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 KM64YNX
Plate since	2019-09-29
Current registration	 KM64YNX
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXXXX
Date of agreement	XXXXXXXXXX	XXXXXX
Agreement type	XXXXXXXXXX	XXXXXX
Agreement term	XXXXXXXXXX	XXXXXX
Agreement number	XXXXXXXXXX	XXXXXX
Contact info	XXXXXXXXXX	XXXXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-18
Last registration	2023-06-26
Complete history	See info



Registration #1	2014-12-18	12 mi
Registration #2	2017-10-05	31.326 mi
Registration #3	2018-10-24	39.017 mi
Registration #4	2018-10-24	39.018 mi
Registration #5	2019-10-22	44.667 mi
Registration #6	2019-10-29	44.680 mi
Registration #7	2020-12-12	48.706 mi
Registration #8	2020-10-29	50.277 mi
Registration #9	2020-10-29	50.277 mi
Registration #10	2020-10-29	50.277 mi
Registration #11	2020-10-29	50.277 mi
Registration #12	2020-10-29	50.277 mi
Registration #13	2020-10-29	50.277 mi
Registration #14	2020-10-29	50.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254