



WM150TZ

report date: 2024-03-28

General information

Make	FIAT
Model	FIORINO 16V MULTIJET
Colour	White
Year of manufacture	2015
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2

Date 2021-10-13

Pictures 11

Listing price [View report](#)



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date 2021-06-11

Pictures 36

Listing price [View report](#)



source: [yesauto.com](https://www.yesauto.com)



MOT history

MOT expiry date	2024-08-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	17
Total items failed	10

MOT #9	2023-08-10 13:45
MOT test number	753896868183
Result	✓ Passed
Next expiry date	2024-08-09
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust box corroded
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8	2023-08-08 10:07
MOT test number	835142818918
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Upper suspension mount, bearing partially siezed
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Upper suspension mount, bearing partially siezed
Advice	Exhaust box corroded
Fail	Offside Obligatory mirror insecure (3.3 (b) (ii))

**MOT #7**

2023-07-11 16:43

MOT test number

161106886203

Result**✗ Failed**

Fail Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Macpherson strut top bush or bearing has excessive wear or free play Rough (5.3.4 (a) (i))

Fail Fuel system component leaking injector (6.1.3 (b) (i))

Advice Vehicles internal headlight adjuster altered to recheck lights

Fail Nearside Front Macpherson strut top bush or bearing has excessive wear or free play Rough (5.3.4 (a) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6

2022-07-12 16:37

MOT test number

885680204524

Result**✓ Passed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

**MOT #5** 2022-07-01 10:26**MOT test number** 152767192082**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed 185/65/15 (5.2.3 (d) (ii))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Fail** Fuel system component leaking Injectors (6.1.3 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #4** 2021-07-08 17:01**MOT test number** 815815751159**Result** ✓ Passed**MOT #3** 2020-11-13 14:17**MOT test number** 109532866080**Result** ✓ Passed**MOT #2** 2019-05-28 13:49**MOT test number** 249758681367**Result** ✓ Passed**MOT #1** 2018-05-24 15:55**MOT test number** 908487768245**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 November 2024

✓
MOT

Expires:
9 August 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-05-29
Last registration	2023-08-10
Complete history	See info



Registration #1	2015-05-29	22 mi
Registration #2	2018-05-24	37.380 mi
Registration #3	2019-05-28	54.260 mi
Registration #4	2020-11-13	69.425 mi
Registration #5	2021-07-08	73.474 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		
Registration #11		
Registration #12		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	5579485