



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 270 CDI INSPIRATION
Colour	Black
Year of manufacture	2004
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	370 Nm at 1.600 rpm
Engine capacity	2.688 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	35.3 mpg
Consumption combined	29.7 mpg
CO2 emission	241 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-24
Pictures	11
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2023-08-03
MOT pass rate	60 %
MOT passed	15
Failed MOT tests	10
Total advice items	37
Total items failed	23

MOT #25	2022-07-20 10:25
MOT test number	597007499855
Result	✓ Passed
Next expiry date	2023-08-03
Advice	Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))

MOT #24	2022-07-20 10:25
MOT test number	763090640762
Result	✗ Failed
Advice	Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))
Pass with rectification	Front Registration plate missing (0.1 (a))

MOT #23	2021-07-30 14:34
MOT test number	496613218655
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #22** 2021-07-28 10:26**MOT test number** 773695506947**Result** ✗ Failed**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Side repeater not working (4.4.1 (a) (ii))**MOT #21** 2020-08-04 12:10**MOT test number** 998875595373**Result** ✓ Passed**MOT #20** 2019-07-29 14:57**MOT test number** 898402716045**Result** ✓ Passed**MOT #19** 2018-07-03 10:56**MOT test number** 639508024010**Result** ✓ Passed

**MOT #18** 2018-06-30 09:59**MOT test number** 799129570696**Result** ✗ Failed**Fail** Nearside Rear Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #17** 2017-07-01 11:47**MOT test number** 964524941932**Result** ✓ Passed**MOT #16** 2017-07-01 11:46**MOT test number** 330526035937**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #15** 2016-07-30 14:29**MOT test number** 432853996304**Result** ✓ Passed

**MOT #14** 2016-07-21 13:02**MOT test number** 722831703601**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #13** 2015-07-22 09:27**MOT test number** 319103205206**Result** ✓ Passed**MOT #12** 2015-07-18 12:15**MOT test number** 385389095158**Result** ✗ Failed**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**MOT #11** 2014-07-16 12:44**MOT test number** 576807294178**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10**

2014-07-14 14:07

**MOT test number**

865965894109

**Result****✗ Failed**

**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

**Advice** Offside Rear Suspension arm has slight play in a ball joint (2.4.G.2)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**Advice** Nearside Rear Suspension arm has slight play in a ball joint (2.4.G.2)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside Stop lamp not working (1.2.1b)

**MOT #9**

2013-07-19 14:38

**MOT test number**

206390903279

**Result****✓ Passed**

**Notice** O/S/F Anti roll bar bush worn.

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #8**

2012-05-10 17:34

**MOT test number**

286181732187

**Result****✓ Passed**

**Notice** N/s/f tyre wearing inner edge

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7**

2012-05-10 10:54

**MOT test number**

737891632141

**Result****✗ Failed**

- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Notice** Centre brake light not working
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/f tyre wearing inner edge

**MOT #6**

2011-04-27 09:44

**MOT test number**

299897911159

**Result****✓ Passed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2011-04-27 09:44

**MOT test number**

255177611128

**Result****✗ Failed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Direction indicators slightly discoloured (1.4.A.2f)
- Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



**MOT #4** 2010-04-22 13:30**MOT test number** 481562410151**Result** ✓ Passed

- Notice** Rear brake pads starting to get a bit low
- Notice** O/s/r tyre cracked on sidewall
- Notice** N/s/r tyre wearing on outer edge and cracked on sidewall

**MOT #3** 2010-04-22 13:30**MOT test number** 520852210124**Result** ✗ Failed

- Notice** N/s/r tyre wearing on outer edge and cracked on sidewall
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Notice** Rear brake pads starting to get a bit low
- Notice** O/s/r tyre cracked on sidewall
- Pass with rectification** Nearside Rear Rear position lamp(s) flickers when tapped lightly by hand (1.1.4c)

**MOT #2** 2009-04-16 15:47**MOT test number** 433926909191**Result** ✓ Passed**MOT #1** 2008-04-21 11:16**MOT test number** 341112418102**Result** ✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	<b>KC04WWX</b>
Plate since	2019-06-29
Current registration	<b>KC04WWX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-05-13
Last registration	2022-07-20
Complete history	<a href="#">See info</a>



Registration #1	2004-05-13	10 mi
Registration #2	2008-04-21	46.594 mi
Registration #3	2009-04-16	57.301 mi
Registration #4	2010-04-22	69.787 mi
Registration #5	2011-04-27	84.701 mi
Registration #6	2012-05-10	95.817 mi
Registration #7	2012-05-10	95.817 mi
Registration #8	2013-07-19	110.792 mi
Registration #9	2014-07-14	118.163 mi
Registration #10	2014-07-16	118.163 mi
Registration #11	2015-07-18	121.395 mi
Registration #12	2015-07-22	121.395 mi
Registration #13	2016-07-21	124.864 mi
Registration #14	2016-07-21	124.864 mi
Registration #15	2016-07-21	124.864 mi
Registration #16	2016-07-21	124.864 mi
Registration #17	2016-07-21	124.864 mi
Registration #18	2016-07-21	124.864 mi
Registration #19	2016-07-21	124.864 mi
Registration #20	2016-07-21	124.864 mi
Registration #21	2016-07-21	124.864 mi
Registration #22	2016-07-21	124.864 mi
Registration #23	2016-07-21	124.864 mi
Registration #24	2016-07-21	124.864 mi
Registration #25	2016-07-21	124.864 mi



Dimensions & weight

Width	2190 mm
Height	1820 mm
Length	4710 mm
Wheel base	2820 mm
Kerb weight	2115 kg

Additional information

Fuel tank capacity	83 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	61296330283526