



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-20
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-16
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	55
Total items failed	2

MOT #22	2024-01-04 09:55
---------	------------------

MOT test number	840026752893
-----------------	--------------

Result	✗ Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing side walls cracking (5.2.3 (d) (ii))
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Pass with rectification	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
DANGEROUS	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure side wall perished and = 2.0mm with flat spots on inner part of tread (5.2.3 (d) (ii))
MAJOR	Nearside Front Track rod end ball joint has excessive play and gaitor split (2.1.3 (b) (i))
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both beam images deteriorating (4.1.4 (b))
MAJOR	Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt outer cv gaitor (6.1.7 (g) (ii))

**MOT #21**

2023-01-11 15:18

**MOT test number**

838077717570

**Result**

✓ Passed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2023-01-05 16:07

**MOT test number**

750898390489

**Result**

✗ Failed

- MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19** 2022-01-17 08:32**MOT test number** 288451709594**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**MOT #18** 2022-01-05 09:42**MOT test number** 946405755793**Result** ✗ Failed**MAJOR** Offside Side repeater not working (4.4.1 (a) (ii))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Items removed from driver's view prior to test**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))**MOT #17** 2020-12-21 14:47**MOT test number** 276460397129**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**MOT #16** 2020-12-21 14:47**MOT test number** 881937342847**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #15** 2020-01-02 10:55**MOT test number** 617171100743**Result** ✓ Passed**MOT #14** 2019-07-12 10:32**MOT test number** 813530003472**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #13** 2018-06-20 09:26**MOT test number** 695444587024**Result** ✓ Passed**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12** 2017-07-03 15:37**MOT test number** 817462443072**Result** ✓ Passed**MOT #11** 2016-07-13 14:37**MOT test number** 751838618720**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2015-06-18 10:29**MOT test number** 218359265146**Result** ✓ Passed**Notice** Front brake disc inner surfaces pitted**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres wearing thin**MOT #9** 2014-07-11 12:22**MOT test number** 316982194146**Result** ✓ Passed**MOT #8** 2013-07-01 15:24**MOT test number** 159202083127**Result** ✓ Passed**MOT #7** 2012-06-14 09:01**MOT test number** 897056862162**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #6** 2011-07-01 09:34**MOT test number** 275152781480**Result** ✓ Passed**Advice** Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Advice** Offside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

**MOT #5** 2010-07-05 12:24**MOT test number** 951216580153**Result** ✓ Passed**Advice** Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Advice** Offside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**MOT #4** 2009-07-10 11:37**MOT test number** 280781599430**Result** ✓ Passed**MOT #3** 2008-07-07 10:17**MOT test number** 612209988102**Result** ✓ Passed**MOT #2** 2007-07-13 13:15**MOT test number** 234194797192**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-07-08 10:45**MOT test number** 802219086101**Result** ✓ Passed





Tax & MOT check

X

Untaxed

Tax expired:  
12 January 2024

X

MOT

Expired:  
16 January 2024

Tax status	Expired at 12 January 2024
Days left	109 days too late
MOT expiry date	16 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>KH03PXZ</b>
Plate since	2024-03-29
Current registration	 <b>KH03PXZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-07-11
Last registration	2024-01-04
Complete history	<a href="#">See info</a>



Registration #1	2003-07-11	6 mi
Registration #2	2006-07-08	21.657 mi
Registration #3	2007-07-13	28.599 mi
Registration #4	2008-07-07	34.963 mi
Registration #5	2009-07-10	40.497 mi
Registration #6	2010-07-05	47.735 mi
Registration #7	2011-07-01	53.073 mi
Registration #8	2012-06-14	58.749 mi
Registration #9	2013-07-01	65.537 mi
Registration #10	2014-07-11	72.124 mi
Registration #11	2015-06-18	79.015 mi
Registration #12	2016-07-13	85.074 mi
Registration #13	2017-06-20	91.217 mi
Registration #14	2018-06-20	97.360 mi
Registration #15	2019-06-20	103.503 mi
Registration #16	2020-06-20	109.646 mi
Registration #17	2021-06-20	115.789 mi
Registration #18	2022-06-20	121.932 mi
Registration #19	2023-06-20	128.075 mi
Registration #20	2024-01-04	134.218 mi
Registration #21	2024-01-04	140.361 mi
Registration #22	2024-01-04	146.504 mi
Registration #23	2024-01-04	152.647 mi
Registration #24	2024-01-04	158.790 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

**Engine number**

BFS 009754