



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D5 SE V50
Colour	Blue
Year of manufacture	2006
Top speed	138 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-05-23
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-11-02
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	48
Total items failed	11

MOT #23	2023-10-30 12:28
MOT test number	713514697214
Result	✓ Passed
Next expiry date	2024-11-02
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #22	2022-11-03 10:23
MOT test number	521579152238
Result	✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Rear Coil spring corroded Both (5.3.1 (b) (i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #21**

2022-10-25 13:06

MOT test number

808294155068

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20

2021-01-26 14:50

MOT test number

873724039878

Result**✓ Passed**

- Advice** Both rear indicators faded
- Advice** Offside Rear tyre worn on inner edge
- Advice** Child Seat fitted not allowing full inspection of adult belt

**MOT #19**

2021-01-26 11:03

MOT test number

235646674685

Result**✗ Failed****Advice** Both rear indicators faded**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear tyre worn on inner edge**Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #18**

2020-01-03 14:30

MOT test number

413438850871

Result**✓ Passed****MOT #17**

2019-03-25 15:50

MOT test number

432318334999

Result**✓ Passed****Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**MOT #16**

2019-03-25 12:53

MOT test number

962773824792

Result**✗ Failed****Advice** Direction indicator slightly discoloured both rear (4.4.3 (a))**Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #15**

2018-06-07 08:16

MOT test number

673908682193

Result

✓ Passed

Advice

Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #14

2018-06-05 08:54

MOT test number

547703640907

Result

✗ Failed

Fail

Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

Fail

Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #13

2017-07-26 07:24

MOT test number

344524839259

Result

✓ Passed

Advice

Suspension arm rubber bush deteriorated but not resulting in excessive movement both offside and nearside front lower rear bushes (2.4.G.2)

Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice

Tyre worn close to the legal limit both offside and nearside rear tyres worn on inner edge (4.1.E.1)

**MOT #12**

2017-07-26 07:24

MOT test number

812756639063

Result**✗ Failed****Advice** Tyre worn close to the legal limit both offside and nearside rear tyres worn on inner edge (4.1.E.1)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement both offside and nearside front lower rear bushes (2.4.G.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #11**

2016-10-14 15:56

MOT test number

816273940976

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #10**

2016-10-14 15:56

MOT test number

877542973033

Result**✗ Failed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Inner Brake pad(s) wearing thin (3.5.1g)**MOT #9**

2015-10-09 15:44

MOT test number

123534123295

Result**✓ Passed****Advice** Nearside Rear Child seat fitted not allowing full inspection of adult seat belt

**MOT #8** 2014-09-24 14:21**MOT test number** 306997164207**Result** ✓ Passed**Advice** Offside Seat belt stitching slightly frayed (5.2.2b)**Notice** BOTH FRONT TYRES STARTING TO WEAR ON THE INNER EDGES**Notice** REAR BRAKE PADS GETTING LOW**MOT #7** 2014-09-24 14:21**MOT test number** 379287464446**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** BOTH FRONT TYRES STARTING TO WEAR ON THE INNER EDGES**Notice** REAR BRAKE PADS GETTING LOW**Advice** Offside Seat belt stitching slightly frayed (5.2.2b)**MOT #6** 2013-09-19 14:16**MOT test number** 785192763211**Result** ✓ Passed**MOT #5** 2012-09-27 12:00**MOT test number** 406181872225**Result** ✓ Passed**MOT #4** 2012-09-27 12:00**MOT test number** 765591272206**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)



MOT #3	2011-09-20 09:26
MOT test number	377373561299
Result	✓ Passed
Notice	Removed sticker from drivers view
Notice	N/s/r tyre starting to mishape
Notice	Front brake pads getting low

MOT #2	2010-09-28 09:09
MOT test number	332331270422
Result	✓ Passed

MOT #1	2009-09-28 09:31
MOT test number	681111579252
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
2 November 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-09-25
Last registration	2023-10-30
Complete history	See info



Registration #1	2006-09-25	19 mi
Registration #2	2009-09-28	27.736 mi
Registration #3	2010-09-28	38.634 mi
Registration #4	2011-09-20	47.171 mi
Registration #5	2012-09-27	56.230 mi
Registration #6	2013-09-19	65.077 mi
Registration #7	2014-09-24	78.191 mi
Registration #8	2015-10-09	84.163 mi
Registration #9	2016-10-14	94.598 mi
Registration #10	2016-10-14	94.598 mi
Registration #11	2017-07-26	104.434 mi
Registration #12	2017-07-26	104.434 mi
Registration #13	2018-05-20	115.277 mi
Registration #14	2018-05-20	115.277 mi
Registration #15	2018-05-20	115.277 mi
Registration #16	2018-05-20	115.277 mi
Registration #17	2018-05-20	115.277 mi
Registration #18	2018-05-20	115.277 mi
Registration #19	2018-05-20	115.277 mi
Registration #20	2018-05-20	115.277 mi
Registration #21	2018-05-20	115.277 mi
Registration #22	2018-05-20	115.277 mi
Registration #23	2018-05-20	115.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4513 mm
Wheel base	2640 mm
Kerb weight	1461 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	395156