



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D SE SPORT
Colour	Blue
Year of manufacture	2007
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	57
Total items failed	19

MOT #21	2023-08-17 13:44
---------	------------------

MOT test number	161273232906
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-08-16
------------------	------------

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2023-08-17 13:44

MOT test number

165509575766

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))

MOT #19

2022-07-23 08:03

MOT test number

769289747445

Result**✓ Passed**

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Centre and rear exhaust boxes in poor condition

MOT #18

2022-07-16 13:39

MOT test number

647420168015

Result**✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Centre and rear exhaust boxes in poor condition

**MOT #17**

2021-08-12 13:39

MOT test number

680926776739

Result

✓ Passed

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #16

2020-10-02 07:20

MOT test number

491651674238

Result

✓ Passed

Advice

Nearside Front Service brake fluctuating, but not excessively more than slight (1.2.1 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Exhaust mounting defective also deteriorated (6.1.2 (a))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slight knock (5.3.4 (a) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened more than slight (1.1.14 (a) (ii))

Advice

Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge below on edge (5.2.3 (e))

Advice

Rear Coil spring corroded offside & nearside (5.3.1 (b) (i))

Advice

Oil leak, but not excessive slight (8.4.1 (a) (i))

**MOT #15**

2020-09-22 08:36

MOT test number

758649117598

Result**✗ Failed**

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust mounting defective also deteriorated (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened more than slight (1.1.14 (a) (ii))
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge below on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement slight knock (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Coil spring corroded offside & nearside (5.3.1 (b) (i))
- Fail** Nearside Headlamp aim too high will not adjust (4.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive slight (8.4.1 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Service brake fluctuating, but not excessively more than slight (1.2.1 (e))

MOT #14

2019-09-03 15:11

MOT test number

200085155570

Result**✓ Passed**

- Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated small cut (6.1.7 (g) (i))
- Advice** Front brake discs deteriorated

**MOT #13**

2019-08-29 13:04

MOT test number

798210566392

Result**✗ Failed****Minor** Nearside Inner Drive shaft joint constant velocity boot severely deteriorated small cut (6.1.7 (g) (i))**Fail** Offside Front Tyre not fitted in accordance with side wall instructions inner - outer (5.2.3 (i))**Advice** Front brake discs deteriorated**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Side repeater incorrect colour (4.4.3 (a))**MOT #12**

2019-06-12 10:19

MOT test number

922988674094

Result**✗ Failed****Advice** Nearside Front Inner Drive shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))**Fail** Offside Rear Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust Surface Corroded**MOT #11**

2018-03-29 13:07

MOT test number

247855162518

Result**✓ Passed**

**MOT #10** 2018-02-03 16:00**MOT test number** 270831709498**Result** ✗ Failed**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Parking brake effort low**Fail** Offside Front coil spring fractured (2.4.C.1a)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Coil spring corroded both rear (2.4.C.1b)**Advice** Exhaust deteriorated**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2016-09-09 12:22**MOT test number** 128528736901**Result** ✓ Passed**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2016-09-09 09:09**MOT test number** 957737018681**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Inner Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #7** 2015-10-08 14:29**MOT test number** 457660216984**Result** ✓ Passed**MOT #6** 2015-10-08 08:29**MOT test number** 292324672003**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)**MOT #5** 2014-09-06 11:30**MOT test number** 325929444460**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**MOT #4** 2013-08-27 17:10**MOT test number** 375629733487**Result** ✓ Passed



MOT #3	2012-09-18 16:38
MOT test number	295452062218
Result	✓ Passed
MOT #2	2011-09-17 10:24
MOT test number	298180661276
Result	✓ Passed
MOT #1	2010-09-20 14:18
MOT test number	322973260244
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 December 2023

✓

MOT

Expires:
16 August 2024

Tax status	Expired at 1 December 2023
Days left	149 days too late
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 KV57XCD
Plate since	2019-09-29
Current registration	 KV57XCD
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-09-19
Last registration	2023-08-17
Complete history	See info



Registration #1	2007-09-19	18 mi
Registration #2	2010-09-20	19.803 mi
Registration #3	2011-09-17	26.737 mi
Registration #4	2012-09-18	32.448 mi
Registration #5	2013-08-27	36.604 mi
Registration #6	2014-09-06	49.254 mi
Registration #7	2015-10-08	65.233 mi
Registration #8	2015-10-08	65.243 mi
Registration #9	2016-09-09	75.287 mi
Registration #10	2016-09-09	75.290 mi
Registration #11	2018-02-03	86.601 mi
Registration #12	2018-03-29	86.651 mi
Registration #13	2019-05-20	95.277 mi
Registration #14	2019-05-20	95.277 mi
Registration #15	2019-05-20	95.277 mi
Registration #16	2019-05-20	95.277 mi
Registration #17	2019-05-20	95.277 mi
Registration #18	2019-05-20	95.277 mi
Registration #19	2019-05-20	95.277 mi
Registration #20	2019-05-20	95.277 mi
Registration #21	2019-05-20	95.277 mi
Registration #22	2019-05-20	95.277 mi
Registration #23	2019-05-20	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1414 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	139688