





report date: 2024-03-29

#### General information

Make	NISSAN
Model	NV200 DCI ACENTA COMBI
Colour	Silver
Year of manufacture	2016
Top speed	98 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-29

## Internet history

#### Entry 1


Date 2021-06-17


Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

## MOT history

MOT expiry date	2025-01-17
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	10
Total items failed	12

MOT #15		2024-01-18 13:12
MOT test	number	877671439697
Result		✓ Passed
Next expiry date 2025-01-		2025-01-17
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))		
Advice	Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))	

MOT #14		2024-	01-18 13:12
MOT test	number	517	7061915944
Result			<b>X</b> Failed
Advice Front Tyre worn close to legal limit/worn on edge both side (5.2.3 (e))			
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))			
Pass wit	h rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #13	2023-07-19 11:54
MOT test number	149314084231
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12

MOT test number

897626186791

Result

Pass with rectification

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11

MOT test number

Result

MOT #10

2023-01-20 14:48

797707900763

✓ Passed

MOT test number 444380189702
Result ✓ Passed

MOT #9

MOT test number

Result

Fail Offside Front Road wheel fixing missing Brocken (5.2.1 (a) (i))

MOT #8

MOT test number

Result

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

✓ Passed

MOT test number

Result

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Horn not working (7.7 (a))

Pass with rectification Nearside Front Headlamp are incorrectly positioned (4.1.4 (a))

MOT #6 2022-01-06 16:45
MOT test number 375554938623

MOT #5 2021-07-08 10:51

**MOT test number** 813253418049

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Parking brake need adjustment

Result

MOT #4 2021-06-08 10:10
MOT test number 219491962614

Result 

Passed

MOT #3 2020-06-08 07:29

**MOT test number** 384507022472

**Result** ✓ Passed

MOT #2 2019-04-27 09:04

**MOT test number** 980819428881

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

## **MOT #1** 2019-04-26 11:07

**MOT test number** 934065023471

MOTTE	954005025471
Result	<b>≍</b> Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail (e))	Central Front Exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3
Fail	Front Exhaust system insecure (6.1.2 (a))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire $(6.1.3 (e))$

CarCheck.co.uk page 6/13



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	17 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

## WO16MSV

report date: 2024-03-29

For how long did the current and previous owner(s) have this NISSAN? How many owners did this have? Check it in the premium report and see all owner registrations. Download the full report he	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
***************************************	
manuse and the same and the sam	
***************************************	
Mor	e info >
Distanch and the second	

## Plate changes

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2016-07-04
Last registration	2024-01-18
Complete history	See info



Registration #1	2016-07-04	24 mi
Registration #2	2019-04-26	27.660 mi
Registration #3	2019-04-27	27.698 mi
Registration #4	2020-06-08	74.326 mi
Registration #5	2021-06-08	86.661 mi
Registration #6		11.777 es
Registration #7	2021-07-08	87.048 mi
Registration #8	2022-01-06	98.656 mi
Registration #9	2022-07-05	109.697 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

## Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	75%
Children	80%
Pedestrian	60%
Safety systems	38%
Overall rating	65%
Video	see crash video



## Dimensions & weight

Width	2011 mm
Height	1860 mm
Length	4400 mm
Kerb weight	1338 kg
Max. allowed weight	2050 kg

## Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number CarCheck.co.uk	D140532 page 13/13