



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Grey
Year of manufacture	2010
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-09
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	36
Total items failed	7

MOT #16	2023-06-06 10:51
MOT test number	385586563856
Result	✓ Passed
Next expiry date	2024-06-09

MOT #15	2022-06-08 12:43
MOT test number	233956557124
Result	✓ Passed

MOT #14	2021-06-10 14:20
MOT test number	930128439184
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2021-06-10 10:08

**MOT test number**

146455020427

**Result****✗ Failed**

- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #12**

2020-10-14 09:38

**MOT test number**

445440918058

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Central Front Exhaust mounting defective dual hanger after flexi (6.1.2 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #11** 2020-10-13 11:24**MOT test number** 634029725855**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Coil spring fractured or broken broken (5.3.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge close to legal limit (5.2.3 (e))**Advice** Central Front Exhaust mounting defective dual hanger after flexi (6.1.2 (a))**Fail** Nearside Rear Coil spring fractured or broken broken (5.3.1 (b) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #10** 2019-09-20 09:38**MOT test number** 258369591811**Result** ✓ Passed**Advice** Exhaust mounting defective front mount behind flexible section (6.1.2 (a))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2018-09-11 15:47**MOT test number** 154302644386**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #8**

2018-09-11 09:28

**MOT test number**

687299008513

**Result**

✗ Failed

**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #7**

2017-09-22 09:52

**MOT test number**

118717872411

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Outer cracked**Advice** Inner faces on both front brake discs corroded and scored**MOT #6**

2016-09-22 08:49

**MOT test number**

310914290229

**Result**

✓ Passed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Centre Rear exhaust heat shield loose**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**MOT #5**

2015-09-28 14:06

**MOT test number**

341727883825

**Result**

✓ Passed



MOT #4	2014-09-23 09:43
MOT test number	366446864494
Result	✓ Passed
MOT #3	2013-09-04 08:39
MOT test number	817217343200
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2013-01-15 10:07
MOT test number	766765613087
Result	✓ Passed
Notice	Rear tyres worn on outer edges
MOT #1	2012-09-28 13:57
MOT test number	679422372280
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
9 June 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	9 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-03-29
Current registration	 
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-18
Last registration	2023-06-06
Complete history	<a href="#">See info</a>



Registration #1	2010-01-18	9 mi
Registration #2	2012-09-28	20.277 mi
Registration #3	2013-01-15	25.471 mi
Registration #4	2013-09-04	29.457 mi
Registration #5	2014-09-23	38.474 mi
Registration #6	2015-09-28	42.970 mi
Registration #7	2016-09-22	44.250 mi
Registration #8	2017-09-22	48.286 mi
Registration #9	2018-09-11	50.643 mi
Registration #10	2019-09-11	51.277 mi
Registration #11	2020-09-11	51.277 mi
Registration #12	2021-09-11	51.277 mi
Registration #13	2022-09-11	51.277 mi
Registration #14	2023-09-11	51.277 mi
Registration #15	2024-09-11	51.277 mi
Registration #16	2025-09-11	51.277 mi
Registration #17	2026-09-11	51.277 mi
Registration #18	2027-09-11	51.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	AL29261