





report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/13



WJ11PNO

report date: 2024-03-29

Internet history

Entry 3

Date 2021-11-08

Pictures 11

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 2

Date	2021-10-25
------	------------

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1


Date 2021-02-04

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2023-11-08
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	20
Total items failed	6

MOT #14		2022-11-09 12:00
MOT test	number	344747189708
Result		✓ Passed
Next exp	iry date	2023-11-08
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamp	os or light sources (4.7.1
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weake	ned (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weak	kened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13		2021-10-14 16:24
MOT test	number	186835437157
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Brake disc worn, but not excessively all four (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



Result

WJ11PNO report date: 2024-03-29

× Failed

MOT #12 2021-10-14 16:24

MOT test number 120899246823

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Brake disc worn, but not excessively all four (1.1.14 (a) (i))

MOT #11 2020-09-29 08:19

MOT test number 898992441914

Result \square Passed

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2020-09-29 08:19

MOT test number 473949420716

Pass with rectification Nearside Obligatory mirror missing (3.3 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #9 2019-10-18 14:35

MOT test number 183096460528

Result

Passed

MOT #8 2018-10-10 09:18

MOT test number 913329278196

Result

Passed

CarCheck.co.uk page 4/13



MOT #7 2018-10-09 06:47

MOT test number 192207430587

Result × Failed

MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a))

MAJOR Reversing lamp inoperative (4.6.1 (a))

MOT #6 2018-02-12 12:42

MOT test number 377085377975

Advice Under tray fitted

MOT #5 2017-03-10 11:14

MOT test number 686064202237

Result \(\sqrt{Passed} \)

Advice Nearside rear tyre worn on outer edge

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #4 2016-03-11 10:15

MOT test number 840330738914

Result
✓ Passed

MOT #3 2015-03-06 09:34

MOT test number 725855765095

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/13



MOT #2 2014-03-11 14:52 **MOT test number** 258080174045 Result ✓ Passed **MOT #1** 2014-03-10 13:09 **MOT test number** 406779764088 Result × Failed **Notice** Under-trays fitted obscuring some underside components Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 6/13





Tax & MOT check



Tax expired: 1 November 2023

X MOT

Expired: 8 November 2023

Tax status	Expired at 1 November 2023
Days left	181 days too late
MOT expiry date	8 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of sisters	
access of passing	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-03-01
Last registration	2022-11-09
Complete history	See info



Registration #1	2011-03-01	18 mi
Registration #2	2014-03-10	35.467 mi
Registration #3	2014-03-11	35.467 mi
Registration #4	2015-03-06	47.337 mi
Registration #5	2016-03-11	60.779 mi
Registration #6	2017-03-10	74.335 mi
Registration #7	2018-02-12	86.668 mi
Registration #8	2018-10-09	94.018 mi
Registration #9	2018-10-10	94.018 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	e 13/13

Number of axles 2

Engine number D246598