





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Red
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-15
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	17
Total items failed	13

MOT #12		2024-04-02 13:10
MOT test	number	128260439443
Result		✓ Passed
Next expi	ry date	2025-04-15
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #11	2024-04-02 08:38
MOT test number	390261649859
Result	× Failed
Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no lor of dirt (6.1.7 (g) (ii))	nger prevents the ingress
Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Fail Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))	
Fail Nearside Front Steering linkage ball joint has excessive play (2.1.3 (b) (i))	
Advice Nearside Rear Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/13



SC64VXZ

report date: 2024-03-28

MOT #10 2023-04-11 11:56

MOT test number 703493891163

Result ✓ Passed

MOT #9 2023-04-11 08:01

MOT test number 218405728364

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2022-03-31 09:26

MOT test number 834720849351

Advice Rear Brake pipe corroded, covered in grease or other material axle (1.1.11 (c))

Advice Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #7 2022-03-31 09:26

MOT test number 412134105889

Result X Failed

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

Advice Offside Front Outer Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Pass with rectification Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Rear Brake pipe corroded, covered in grease or other material axle (1.1.11 (c))

MOT #6 2021-04-16 08:52

MOT test number 488011507754

Result
✓ Passed

CarCheck.co.uk page 4/13



SC64VXZ

report date: 2024-03-28

2020-02-13 14:50 **MOT #5 MOT** test number 154080721149 Result ✓ Passed MOT #4 2020-02-12 11:57 **MOT** test number 106420087662 Result × Failed Fail Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

MOT #3		2019-02-18 12:45
MOT test	number	339974353259
Result		✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Coolant low	

MOT #2		2018-02-13 14:40
MOT test	number	546068254873
Result		✓ Passed
Advice	Nearside Child Seat fitted not allowing full inspection of adult belt	
Advice	Parking brake lever has little reserve travel (3.1.6b)	

CarCheck.co.uk page 5/13



MOT #1 2017-02-17 13:40

MOT test number 283281368425

Result ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-31
Last registration	2024-04-02
Complete history	See info



Registration #1	2014-12-31	27 mi
Registration #2	2017-02-17	8.934 mi
Registration #3	2018-02-13	14.125 mi
Registration #4	2019-02-18	37.668 mi
Registration #5	2020-02-12	22.869 mi
Registration #6	2020-02-13	22.872 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		91,700 esi
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2
Engine number U165424